

2009 AIR ACCIDENTS/INCIDENTS

ACCIDENT INVESTIGATION BRANCH Ministry of Infrastructure Development

	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER AGE & EXPERIENCE	OPERATOR	CIRCUMSTANCES OF ACCIDENT
1	CESSNA 185 AMPHIBIOUS N341EA	22.1.2009 1030HRS	LAKE VICTORIA, OFF NANSIO HARBOUR, UKERWE ISLAND	Capt. DALE HAMILTON 55 YRS 3500 HRS	AIM AIR MWANZA	Aircraft tipped upside down on touching water. Landing on water was initiated with the landing gear extended. INJURIES: Fatal 0 Serious 0 None 1
2	PA34-200T 5H-AZT	7.3.2009 0610 HRS	MTEMERE AIRSTRIP SELOUS GAME RESERVE	P. MWASANJOBE 56 YRS 14,000 HRS	ZANAIR ZANZIBAR	Nose landing gear collapsed when the aircraft was taxiing for takeoff. INJURIES: Fatal 0 Serious 0 None 3
3	ALOUETTE III HELICOPTER ZS-RYU	4.3.2009 0610 HRS	NORTH MARA GOLD MINE, TARIME			Aircraft executed a heavy landing. INJURIES: Fatal 0 Serious 0 None 3
4	ATR 72 5H-PWA	29.3.2009 1050 HRS	ENROUTE MWANZA- KIA	MOSHA O.A. 51 YRS 20,000 HRS	PRECISIONAIR	Commander collapsed on the controls. Aircraft returned to Mwanza and landed safely. INJURIES: Fatal 0 Serious 0 None 46
5	CESSNA 206 5H-MPD	29.5.2009 0909 HRS	RWY 23 JULIUS NYERERE INTERNATIONAL	CAPT. AGUSTINO SHIA 30 YRS 379 HRS	TANZANIA POLICE AIRWING	ACFT veered off the runway after touchdown on RWY 23. Nose landing gear struck a drainage trench and collapsed. INJURIES: Fatal 0 Serious 0 None 1
6	CESSNA 182 5H-MZR	30.5.2009 1012 HRS	RWY 23 JULIUS NYERERE INTERNATIONAL	CAPT. HAMZA SAIDI ALI 22YRS 278 HRS	KINASI LTD DAR ES SALAAM	ACFT veered off the runway after touchdown on RWY 23. Nose landing gear struck a drainage trench and collapsed. INJURIES: Fatal 0 Serious 0 None 4

7	CESSNA F406 5H-TZE	14.3.2009 0530 HRS	ENROUTE DAR-MWANZA	CAPT. LENNART TAUBE	TANZANAIR DAR ES SALAAM	The commander fell sick and became momentarily incapacitated. The co-pilot took over the controls. The flight returned to Dar es Salaam where it landed safely. INJURIES: Fatal 0 Serious 0 None 4
8	PA34-200T 5H-AZT	12.7.2009 0610 HRS	SIWANDU AIRSTRIP SELOUS GAME RESERVE	Capt. Tom HOBSON 30YRS 1700HRS	ZANAIR ZANZIBAR	Aircraft suspected to have made a heavy landing. Damage to nose landing gear and fuselage forward of windshield. INJURIES: Fatal 0 Serious 0 None 2
9	CESSNA 206 5H-LAI	16.8.2009 1201 HRS	RWY 23 JULIUS NYERERE INTERNATIONAL	Capt. BARIN TOHID 29 YRS 700 HRS	FLIGHT LINK DAR ES SALAAM	ACFT veered off the runway after touchdown on RWY 23. Right wing and propeller struck the ground. Aircraft substantially damaged. INJURIES: Fatal 0 Serious 0 None 1
10	PA34-200T 5H-AZT	21.9.2009 0555 HRS	MTEMERE AIRSTRIP SELOUS	Capt. Tom HOBSON 30 YRS 1700HRS	ZANAIR ZANZIBAR	Nose landing gear collapsed during the landing roll. INJURIES: Fatal 0 Serious 0 None 1
11	CESSNA 208B 5H-FOX	12.11.2009 0419 HRS	JONGOMERO AIRSTRIP RUAHA NATIONAL PARK	Capt. MENDIGUETI PETRAGIA Silvana Karina. 43 YRS 3900 HRS	FLY SAFARI AIR LINK. DAR ES SALAAM	ACFT collided with a tree and crashed shortly before touchdown. Low cloud prevailed. INJURIES: Fatal 0 Serious 0 None 2
12	CESSNA 210N 5H-MVO	22.11.2009 0735 HRS	LUDODOLELO AIRSTRIP MAKETE DISTRICT	Capt. SVAN VOIGT 24 YRS 1400 HRS	SAFARI AIR LINK DAR ES SALAAM	ACFT overran the runway and crashed during a failed go around. INJURIES: Fatal 0 Serious 0 Minor 3 None 1
13	PA 28-140 5H-TFD	26.11.2009 0727 HRS	JNIA DAR ES SALAAM	N.S. Abdallah 22 YRS 35 HRS	TROPICAL FLYING SCHOOL DAR ES SALAAM	A learner pilot was trying to land against a cross wind. The aircraft swerved off the runway damaging the nose landing gear and the propeller. INJURIES: Fatal 0 Serious 0 Minor 1

14	CESSNA 208B 5H-NBL	29.12.2009 1215 HRS	MATAMBWE AIRSTRIP SELOUS	Cpt. G. Mwela 64 YRS 16,000 HRS?	ZANTAS DAR ES SALAAM	During the landing roll the aircraft swerved off the runway to avoid a deep trench across the runway that was straight ahead. The aircraft sunk in mud, causing a propeller strike. There were El Niño rains in the area. INJURIES: Fatal 0 Serious 0 None 1
15	BEECH BE 200 KINGAIR 5Y- FDK	29.12.2009	LUPITA KIPILI AIRSRIP RUKWA	Capt. William Keeling Wood 53 YRS 14,200HRS	PHOENIX AVIATION NAIROBI	Aircraft sunk in soft soil during landing roll. Propeller strike. There were El Niño rains in the area. INJURIES: Fatal 0 Serious 0 None 10