

2006 AIR ACCIDENTS/INCIDENTS

ACCIDENT INVESTIGATION BRANCH Ministry of Infrastructure Development TANZANIA CIVIL AVIATION AUTHORITY

No.	TYPE REGISTRATIO N ENGINES YR OF MANUF.	DATE & TIME UTC	LOCATION	COMMANDER AGE LICENSE EXPERIENCE	OPERATOR	CIRCUMSTANCES OF ACCIDENT AND DAMAGE TO AIRCRAFT
1. AC	PA34-200T 5H-ARP 2 TCM TSIO- 540E 1975	3.2.2006 0707HRS	RAS KUTANI AIRSTRIP 30 KM SOUTH OF DAR	H.S.MAQBUL 28YRS CPL 2600HRS	COASTAL TRAVELS DAR ES SALAAM	A/C OVERRAN RWY IN STRONG CROSS WIND AND STRUCK A ROAD DRAINAGE TRENCH. A/C SUBSTANTIALLY DAMAGED. INJURIES: Fatal 0 Serious 0 none 3
2 AC	CESSNA 402B 5H-ZAL 2 TCM TSIO- 540E 1974	8.3.2006 0707 HRS	NYAMONGO AIRSTRIP 115 nm N.W. of MWANZA	MICHAEL MUZENZE 51 YEARS CPL 12 000 HRS	AURIC AIR MWANZA	A/C OVERRAN RWY DURING LDG ROLL DUE TO LATE TOUCH DOWN. NOSE LDG GEAR COLLAPSED. DAMAGE TO PROPS, FUSELAGE UNDERSIDE AND NOSE LDG GEAR. INJURIES: Fatal 0 Serious 0 None 7
3. AC	PILATUS PC12 5H-EXC ONE PT6A-67B 1998	31.3.2006 1045 HRS	BUHEMBA AIRSTRIP MARA REGION	RICHARD STRATTEN 42 YEARS CPL 10,300 HRS	COASTAL TRAVELS DAR ES SALAAM	A/C WAS ATTACKED WITH HAND GRENADES AND RIFLE FIRE ON THE APRON SHORTLY BEFORE DEPARTURE. BANDITS OFF LOADED CARGO OF GOLD AND ESCAPED BY ROAD IN HIJACKED MINING VEHICLE. A/C EXTENSIVELY DAMAGED BY SHRAPNEL & GUN FIRE. INJURIES: Fatal 0 Serious 0 None 3
4. MS	CESSNA 208 5H-ZBZ ONE PT6A-114A 1991	13.4.2006 1130 HRS	HAYDOM AIRSTRIP MANYARA REGION	STEPHAN SCHRAMM 50 YEARS CPL 4954 HOURS	MISSION AVIATION FELLOWSHIP DODOMA	A/C SWERVED OFF THE RUNWAY DURING FLARE AND, COLLIDED WITH TREES IN BAD WEATHER. A/C EXTENSIVELY DAMAGED. PROBABLE WRITE OFF. INJURIES: Fatal 0 Serious 0 None 9
5 UN	LOCKHEED C-130 S9-BOF 4RR ALLISON 501 D22 A 1975	12.7.2006 1217 HRS	KIGOMA AIRPORT	ARTURO SANTOS 64 YRS ATPL 26,000 HRS	MONUC UNITED NATIONS MISSION IN THE DRC	A/C RAN OUT OF CONTROL AND CRASHED FOLLOWING ATTEMPTED OVERSHOOT WITH FULL FLAPS. A/C COMPLETELY DESTROYED BY POST IMPACT FIRE INJURIES Fatal 0 Serious 0 Minor 1 None 4

6 TR	PA 31-325 5H-ILS 2 LYCOMING LTIO 540 F2BD 1981	25.7.2006 0800 HRS	KILIMANJARO INTERNATIONAL	BARAKA 24 YRS CPL 369 HOURS	TANZANIA GOVT FLIGHT AGENCY	ON OVERSHOOT LEFT PROPELLER TOUCHED THE GROUND. BLADES TIPS BENT. BELLY ANTENNAS DAMAGED. INJURIES: Fatal 0 Serious 0 None 2
7 AC	ZS-NPK ONE TCM TSIO 520 1979	26.7.2006 1302 HRS	MWANZA AIRPORT	ANDRE DE VILLIERS 45 YRS RSA CPL 450 HRS	COASTAL TRAVELS KILWA AIR	ZS-NPK COLLIDED WITH UNOCCUPIED C208, 5H-JOE PARKED ON APRON. ITS FIN DAMAGED 5H-JOE AILERON TRIM TAB & WING UNDER SURFACE. DAMAGE TO NPK CONFINED TO ROTATING BEACON AND FAIRING. INJURIES: Fatal 0 Serious 0 None 2
8 AC	BEECH BE 200 KINGAIR 5H-TZX 2 PT6A-42 1985	10.8.2006 1406 HRS	MOROGORO AIRSTRIP	CAPT. KONDO 52 YRS ATPL 18300 HRS	TANZANAIR	LEFT PROPELLER HIT A CONCRETE TIE DOWN BLOCK ON APRON. DAMAGE CONFINED TO LEFT PROPELLER. INJURIES: Fatal 0 Serious 0 None 1
9 AC	CESSNA 404 5H-RAY 2 TCM GTSIO 520M 1976	11.9.2006 1225 HRS	LWAFI AIRSTRIP MPANDA	CAPT. AMIN 49 YRS CPL 4000 HRS	TWIN WINGS	A/C FAILED TO CLIMB AND COLLIDED WITH TREES ON THE FLIGHT PATH. PILOT USED FULL FLAPS FOR TAKE OFF AND ROTATED AT 65 KT. A/C COMPLETELY DESTROYED BY IMPACT. INJURIES: Fatal 0 Serious 0 None 5
10 AC	BN2A -9 ISLANDER 5H-UNT 2 LYCOMING O-540-I4C5 1976	15.9.2006 1212 HRS	NANGUNGU, MONDULI ARUSHA	GAT JOLLY S 32 YRS RSA CPL WITHOUT TANZANIA CAA VALIDATION 640 HRS	SAFARI EXPRESS AIRWAYS ARUSHA	FUEL RAN OUT IN FLIGHT, BOTH ENGINES STOPPED. A/C FORCE LANDED IN BUSH LAND. DAMAGE CONFINED TO LEFT MAIN LANDING GEAR INJURIES: Fatal 0 Serious 0 None 7
11 PVT	BEECH 35-33 5H-SRM ONE TCM IO 470-J 1960	23.11.2006 1225 HRS	SELOUS GAME RESERVE Nr KINYANGURU RAILWAY STATION	CLIFF KACUNGIRA 51 YRS CPL 9000 HRS	S.R. MINERALS DAR ES SALAAM	ENGINE STOPPED IN FLIGHT DUE TO FUEL MISMANAGEMENT. AIRCRAFT FORCE LANDED IN BUSH LAND. A/C EXTENSIVELY DAMAGED. PROBABLE WRITE OFF. INJURIES: Fatal 0 Serious 0 None 1
12 AC	PIPER PA 34- 200T 5H-SAY 2 TCM TSIO 360-EBI4 1978	24.10.2006 0416 HRS	M.J.K. NYERERE INT. AIRPORT DAR ES SALAAM	BARAKA RUTWAZA 34 YRS CPL 1867 HRS	COASTAL TRAVELS DAR ES SALAAM	AIRCRAFT EXECUTED WHEELS UP LANDING. DAMAGE TO BOTH PROPS AND FUSELAGE UNDERSIDE. INJURIES: Fatal 0 Serious 0 None 5

13	PIPER PA 31-350 5H-SNS 2 LYCOMING TIO 540 J2BD 1981	16.11.2006 1124 HRS	EN-ROUTE NJOMBE – DAR ES SALAAM	CAPT. KIKULI 7800 HRS CPL 61 YRS	TANZANAIR	DOUBLE ENGINE FAILURE IN FLIGHT ONE ENGINE RE-STARTED. A/C LANDED SAFELY AT DAR. ALL FUEL TANKS FOUND EMPTY. NO DAMAGE TO THE A/C INJURIES: Fatal 0 Serious 0 None 4
14	CESSNA 310R 5H-TZA 2 TCM IO 520 MB 1978	16.12.2006 0654 HRS	NEAR MBEYA AIRPORT	MARTIN SUMARI 59 YRS CPL 7400 HRS 59 YRS	TANZANAIR	AIRCRAFT FAILED TO CLIMB AND COLLIDED WITH BUILDINGS SHORTLY AFTER TAKE OFF. A/C WAS OVERLOADED AND WAS PREMATURELY ROTATED. A/C COMPLETELY DESTROYED BY IMPACT AND THE SUBSEQUENT FIRE. INJURIES: Fatal 4 Serious 2 None 0

SHADING INDICATES ACCIDENT UNSHADED ROWS REPRESENT INCIDENTS

A/C : AIRCRAFT,
RWY: RUNWAY,
LDG: LANDING,

AC: AIR CHARTER
MS: MISSIONARY FLIGHT
PVT: PRIVATE FLIGHT

TR: TRAINING FLIGHT
UN: UNITED NATIONS RELIEF OPERATIONS

