

2007 AIR ACCIDENTS/INCIDENTS

ACCIDENT INVESTIGATION BRANCH Ministry of Infrastructure Development TANZANIA CIVIL AVIATION AUTHORITY

	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER, AGE & EXPERIENCE	OPERATOR	CIRCUMSTANCES OF ACCIDENT
1.	PA34-31-310 5H-MUX	5.1.2007 0902 HRS	MATAMBWE AIRSTRIP 93 nm SW OF DAR	M.S. MBAROUK 27YRS 1,700 HRS	DJB Ltd DAR ES SALAAM	A/C COLLIDED WITH TREES BEYOND RWY IN AN ATTEMPTED TAKE OFF FOLLOWING AN UNSUCCESSFUL LANDING INJURIES: Fatal 1 Serious 2 None 8
2.	PA32-300 5H-SKY	28.1.2007 1220 HRS	CHUNYA AIRSTRIP MBEYA REGION	JEAN PIERRE 50 YRS 800 HRS	SKY AVIATION DAR ES SALAAM	A/C FAILED TO CLIMB AFTER TAKE OFF, CRASHED 120 METRES BEYOND RWY. A/C DESTROYED. INJURIES: Fatal 0 Serious 0 None 3
3	CESSNA 150 5Y-AWZ	1.4.2007 1330HRS	WOSIWOSI AIRSTRIP NR LAKE NATRON MANYARA REGION	CAPT. MURUITHI 26 YRS 52 HRS	PEGASUS FLIERS NAIROBI WILSON	DURING LDG ROLL A/C SWERVED OFF RUNWAY AND COLLIDED WITH A TREE WHILST AVOIDING A ZEBRA. INJURIES: Fatal 0 serious 0 None 1
4	BOEING 737-300 7Q-YKP	18.4.2007 1008 HRS	JULIUS NYERERE INT. AIRPORT DAR ES SALAAM	CAPT. 4 2YRS 4500 HRS	AIR MALAWI	WHEN REVERSE THRUST WAS SELECTED ONE SET OF CASCADING VANES SEPARATED TEARIND A PIECE OF ENGINE NACELLE. BOTH FELL ON THE RWY. INJURIES: Fatal 0 serious 0 None 102

