

2010 AIR ACCIDENTS/INCIDENTS

ACCIDENT INVESTIGATION BRANCH Ministry of Works

	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER AGE & EXPERIENCE	OPERATOR	CIRCUMSTANCES OF ACCIDENT
1	CESSNA 172E 5H-MZR	27.1.2010 1351 HRS	KIWENGWA, North East ZANZIBAR	Capt. HAMZA SAIDI 22 YRS 478 HRS	KINASI ZANZIBAR	Aircraft force landed on a road following engine trouble. INJURIES: Fatal 0 Serious 0 None 2
2	PA34-200T 5H-AZT	28.1.2010 0900 HRS	MTEMERE AIRSTRIP SELOUS GAME RESERVE	RISTA KAPLAN NICOLAS 26 YRS 1280 HRS	ZANAIR ZANZIBAR	Nose landing gear collapsed when the aircraft was taxiing. ACFT substantially damaged. INJURIES: Fatal 0 Serious 0 None 5
3	CESSNA 206H 5H-TPN	5.2.2010 1430 HRS	MAHALE AIRSTRIP KIGOMA	Capt. PIUS KAJWANGYA 43 YRS 5,600 HRS	TANZANIA NATIONAL PARKS ARUSHA	During landing roll the aircraft overran the end of the runway. Nose landing gear struck a terrace and collapsed. ACFT tipped on its back. ACFT destroyed. INJURIES: Fatal 0 Serious 1 None 2
4	BOEING 737-247 5H-MVZ	1.3.2010 0449HRS	RUNWAY 30 MWANZA AIRPORT	Capt. MWAKANG'ATA 52 YRS 8,500 HRS	AIR TANZANIA DAR ES SALAAM	During the landing roll the aircraft veered to the left and exited the rwy. Nose landing gear collapsed. INJURIES: Fatal 0 Serious 0 None 46
5	BELL 206B 5H-MWK	2.6.2010 1430 HRS	MALANGALI HILL MBEYA	Capt. BARASA R.S. 41 YRS 1150 HRS	KEYS AVIATION LTD MOSHI	ACFT made a heavy landing after the flight was aborted due bad weather. INJURIES: Fatal 0 Serious 0 None 3
6	CESSNA 206 5H-MVI	28.7.2010 1212 HRS	EN-ROUTE MIKUMI - SIWANDU	Capt. KJETIL Torvestad ASPEN 25 YRS 1,600 HRS	SAFARI AIR LINK DAR ES SALAAM	ACFT force landed in a forest following engine failure. INJURIES: Fatal 0 Serious 0 None 3

7	CESSNA 206 5H-TCC	31.8.2010 1300 HRS	SUMBAWANGA AIRPORT	NAUDE van RENSBURG 23 YRS 660 HRS	FLIGHT LINK DAR ES SALAAM	ACFT force landed shortly after take-off. Wind shear suspected. INJURIES: Fatal 0 Serious 0 None 3
8	HOT AIR BALLOON 5H-MVM	29.9.2010 0530 HRS	SOROI PLAIN SERENGETI	FRANK BELLATONE 40 YRS 2900 HRS	SERENGETI BALLOON SAFARI ARUSHA	The balloon executed a heavy landing in bad weather. INJURIES: Fatal 2 Serious 8 None 1
9	PA 28-140 5H-TFS	22.10.2010 0700 HRS	CHAU/MTENDE MAKUNDUCHI Southern ZANZIBAR	KEYVAN 40 YRS 1200 HRS	TROPICAL FLYING SCHOOL ZANZIBAR	ACFT crash landed in a bush whilst practicing emergency landing following engine failure INJURIES: Fatal 0 Serious 0 None 2
10	CESSNA 206 5H-ASA	28.10.2010 1200 HRS	ENROUTE ENTEBBE -MWANZA. Aircraft Force landed at Ukerewe	GASTON SHIO 31 YRS 1000 HRS	MT. MERU PETROLEUM LTD ARUSHA	ACFT force landed following engine problem. INJURIES: Fatal 0 Serious 0 None 3
11	CESSNA 406 5H-PAY	28.10.2010 0950 HRS	ZANZIBAR INT. AIRPORT	AMIN MUHIDYN 53 YRS 5127 HRS	TWIN WINGS ZANZIBAR	Nose landing gear collapsed shortly after touchdown. INJURIES: Fatal 0 Serious 0 None 1
12	PA34-200-2 5H-MCU	16.12.2010 1030 HRS	Julius Nyerere Int. Airport DAR ES SALAAM	STEVEN MHINA 36 YRS 500 HRS	BOLD AVIATION DAR ES SALAAM	During attempted landing both propellers struck the tarmac. The aircraft overshot the runway and landed 17 minutes later. INJURIES: Fatal 0 Serious 0 None 6
13	CESSNA 206 5H-PCN	18.12.2010 10940HRS	UYOLE FARM Near MBEYA AIRPORT	KEYVAN KASIZABE 40 YRS 1350 HRS	AIR Z ZANZIBAR	Aircraft failed to climb and force landed shortly after takeoff from runway 13. INJURIES: Fatal 0 Serious 1 None 3*

Fatal Accident

* This was a medical evacuation flight. One passenger, who was an ICU patient, was not injured in the accident but died

shortly after the accident. This is not a fatal accident because the passenger did not die from accident injuries.

Hull loss

