



FAX: (255 22) 2124914, 2118905
PHONE: (255 22) 2115079/80, 2111951.
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
P.O. Box 2819, DAR ES SALAAM
Tetex House, 4th Floor, Pamba Road

AIP
Supplement 04-07/11

1 January 2011

Document No:
TCAA/FRM/ANS/AIS-56

Title: **AIP Supplement**

Page 1 of 1

EN-ROUTE (ENR)

S04 Dar es Salaam FIR – HTDC

SG 352 KHz NDB Operating but subject to interruption due power

(Cancel NOTAM A0351/10)

AERODROMES (AD)

S06 Dar es Salaam International Airport – HTDA

ATIS 119.0 MHz Out of service.

(Cancel NOTAM A0350/10)

S07 Dodoma – HTDO

Fuel JET A1 available only for light aircraft by over wing refueling system.

(Cancel NOTAM B0002/11)