



FAX: (255 22) 2124914, 2118905
 PHONE: (255 22) 2115079/80, 2111951.
 AFS: HTDQYOYO
 Email: tcaa@tcaa.go.tz,
ais@tcaa.go.tz
 Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
 TANZANIA CIVIL AVIATION AUTHORITY
 Aeronautical Information Services
 P.O. Box 2819, DAR ES SALAAM
 Tetex House, 4th Floor, Pamba Road

AIP

Supplement 06-09
 31 July 2008

EN – ROUTE (ENR)

S 06 Dar es Salaam FIR - HTDC

With effect from 25 August 2008, air operators will be required to indicate RVSM Status on all the flight plans filed.

(Refer AIC 6/2008)

S 07 Dar es Salaam FIR - HTDC

During the switch over, operation on non RVSM approved aircraft above FL 410 will be suspended from 2201 on 24 September 2008 to 0200 on 25 September 2008 UTC.

(Refer AIC 6/2008)

S 08 Dar es Salaam FIR - HTDC

With effect from 24 September 2008 at 2201 UTC, flights of non RVSM approved civil aircraft will be prohibited within the Dar es Salaam FIR RVSM airspace (FL 290 and FL410 inclusive).

(Refer AIC 6/2008)

S 09 Dar es Salaam FIR - HTDC

With effect from 25 September 2008, the applicable Flight Level Allocation Scheme (FLAS) will be as follows:-

Westbound 180°-359°	Eastbound 000°-179°
FL400	FL410
FL380	FL390
FL360	FL370
FL340	FL350
FL320	FL330
FL300	FL310
	FL290

However, there will be a suspension of allocation of East Bound Flight levels 310,350 and 390 from 0001 to 0200 on 25 September 2008 UTC.

(Refer AIC 6/2008)

..... **END**.....