



FAX: (255 22) 2124914, 2118905
PHONE: (255 22) 2115079/80, 2111951.
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
P.O. Box 2819, DAR ES SALAAM
Tetex House, 4th Floor, Pamba Road

AIP
Supplement 08 -14/10

26 Aug 2010

Document No:
TCAA/FRM/ANS/AIS-56

Title: **AIP Supplement**

Page 1 of 1

AERODROME

S 08 ZANZIBAR KISAUNI– HTZA

Aerodrome operating but caution advised on landing and takeoff due to bird concentration in the vicinity of aerodrome, daily between 0400-1500 UTC.
(Cancel NOTAM A0162/2010).

S 09 ZANZIBAR KISAUNI – HTZA

Instrument Approach Procedures of ZV VOR/DME RWY 18/36 for all aircraft categories have been withdrawn until new procedures are published.
(Cancel NOTAM A0214/2010).

S 11 ARUSHA – HTAR

Runway 09/27 operative but Pilot to exercise caution due loose chipping approximate 1300m from THR runway 09.
(Cancel NOTAM B0085/2010).

S 13 MWANZA – HTMW.

Instrument Approach Procedures of MZ DVOR/DME RWY 12/30 for all aircraft categories have been withdrawn until new procedures are published.
(Cancel NOTAM A0257/2010).

S 14 KILOSA – HTKS

Runway 10/28 closed due swamping
(Cancel NOTAM C0073/2010).