



FAX: (255 22) 2844300, 2844302
PHONE: (255 22) 2198100, 2844291.
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
Nyerere /Kitunda Road Junction,
P.O.Box 2819,
Dar es Salaam

AIP

Supplement
09 - 12
22 November 2007

Document No:
TCAA/FRM/ANS/AIS-56

AIP Supplement

Page 1 of 1

AERODROMES (AD)

S09 Kilimanjaro International Airport - HTKJ

Concentration of birds is reported around the movement area. Pilots are advised to exercise caution on landing, takeoff and taxing
(Cancel NOTAM A0292/07)

S11 Abeid Amani Karume International Airport – HTZA

TWY C available only to aircraft not exceeding all up weight 61,700 KG
(Cancel NOTAM A0280/07)

S12 Julius Nyerere International Airport- HTDA

The brilliance of airfield lighting system is not controlled by TWR due to remote switching panel out of service.
(Cancel NOTAM A0323/07)