



Fax: (255) 22 2844300, 2844302
PHONE: (255) 22 2198100, 2844291
AFS: HTDQYOYO
E-MAIL: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
Nyerere/ Kitunda Road Junction
Aviation House, 1st Floor,
P.O. Box 2819, DAR ES SALAAM

AIP
Supplement 11/11
17 November 2011

Document No:
TCAA/FRM/ANS/AIS-56

AIP SUPPLEMENT

Page 1 of 1

AERODROMES (AD)

S11 Arusha – HTAR

Pilot are advised to exercise caution during landing on Runway 09 and takeoff Runway 27 due presence of power transmission lines running across the final approach path Runway 09 at approximately 700m from the threshold with a height of 45ft from ground.

(Cancel NOTAM B0070/11)