



FAX: (255 22) 2844300, 2844302  
 PHONE: (255 22) 2198100, 2844291.  
 AFS: HTDQYOYO  
 Email: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz), [ais@tcaa.go.tz](mailto:ais@tcaa.go.tz)  
 Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA**  
**TANZANIA CIVIL AVIATION AUTHORITY**  
 Aeronautical Information Services  
 Nyerere/ Kitunda Road Junction  
 Aviation House, 1st Floor,  
 P.O. Box 2819, DAR ES SALAAM

**AIP**

**Supplement  
 checklist**  
 22 March 2012

Document No:  
 TCAA/FRM/ANS/AIS-16

AIP SUPPLEMENT CHECKLIST

Page 1 of 2

The following AIP supplements at the publication of this checklist are still enforce, Supplements not included in this list have been cancelled, replaced or incorporated in the AIP.

SUPP NO.	DATE	PART OF THE AIP AFFECTED	LOCATION	SUMMARY OF THE CONTENT
10/12	22 Mar 12	Aerodrome(AD)	Tunduru	RWY 11/29 Closed
09/12	22 Mar 12	En-route (ENR)	Mwanza	DVOR changed to MV ( <b>AIRAC</b> )
08/12	22 Mar 12	En-route (ENR)	Dar FIR	Reporting point renamed EPTIK ( <b>AIRAC</b> )
07/12	22 Mar 12	En-route (ENR)	Dar FIR	Reporting point renamed UMTAP ( <b>AIRAC</b> )
06/12	22 Mar 12	En-route (ENR)	Dar FIR	New Route UB530 ( <b>AIRAC</b> )
05/12	23 Feb 12	Aerodrome(AD)	Songwe	New Airport ( <b>AIRAC</b> )
04/12	23 Feb 12	En-route (ENR)	Dar FIR	WGS 84 Coordinates correction
03/12	23 Feb 12	En-route (ENR)	Dar FIR	Dar FIR two Sectors
02/12	23 Feb 12	Aerodrome(AD)	Dodoma	Apron VIP parking Area
01/12	23 Feb 12	En-route (ENR)	Dar FIR	Exchange Rate 2011/2012
13/11	29 Nov 11	En-route (ENR)	Dar FIR	New ATS route UB 533 and B 533( <b>AIRAC</b> )
12/11	29 Nov 11	En-route (ENR)	Dar FIR	New RNAV(RNP 10) Route UT411
11/11	29 Nov 11	Aerodrome(AD)	Arusha	Power transimission lines
10/11	29 Nov 11	Aerodrome(AD)	Dar FIR	Private category Aerodrome Valid Licence
09/11	29 Nov 11	Aerodrome(AD)	Dar and Kili	GNSS Non Precision approach
07/11	01 Jan 11	Aerodrome(AD)	Dodoma	Fuel Jet A1 for small Aircraft
06/11	01 Jan 11	Aerodrome(AD)	Dar	ATIS 119.0 MHz out of service
04/11	01 Jan 11	En-route (ENR)	Songea	SG 352KHZ NDB
20/10	14 Dec 10	Aerodrome(AD)	Zanzibar	New Instrument Approach RWY 36
14/10	26 Aug 10	Aerodrome(AD)	Kilosa	RWY 10/30 closed due swamping
13/10	26 Aug 10	Aerodrome(AD)	Mwanza	IAP of MZ DVOR/DME
11/10	26 Aug 10	Aerodrome(AD)	Arusha	Loose chipping RWY 09/27
09/10	26 Aug 10	Aerodrome(AD)	Zanzibar	IAP of ZV VOR/DME
08/10	26 Aug 10	Aerodrome(AD)	Zanzibar	Bird concentration
10/09	12 Nov 09	En-route (ENR)	Dar FIR	VFR flights
05/09	29 Mar 09	Aerodrome(AD)	Mchauru	Lighting systems
19/08	20 Nov 08	Aerodrome(AD)	Ukerewe	AD Closed
16/08	20 Nov 08	Aerodrome(AD)	Same	Runway15/33 closed
15/08	20 Nov 08	Aerodrome(AD)	Moshi	Runway 18/36 closed
13/08	20 Nov 08	Aerodrome(AD)	Mbeya	Fire fighting and Rescue

This is a controlled document

12/08	20 Nov 08	Aerodrome(AD)	Dar	Concentration t of Birds
11/08	20 Nov 08	Aerodrome(AD)	Dar	Controllers' vision from TWR
13/07	30 Dec 07	Aerodrome(AD)	Dar FIR	AD owned by TANAPA
12/07	22 Nov 07	Aerodrome(AD)	Dar	Lighting system
11/07	22 Nov 07	Aerodrome(AD)	HTZA	TWY C
09/07	22 Nov 07	Aerodrome(AD)	Kilimanjaro	Concentration of Birds
15/06	01 Jan 06	Aerodrome(AD)	Urambo	Runway 12/30
10/06	01 Jan 06	Aerodrome(AD)	Handanjen ga	Airstrip Closed
05/06	01 Jan 06	Aerodrome(AD)	Dar FIR	Detailed Surveyed coordinates