



FAX: (255 22) 2124914, 2118905
PHONE: (255 22) 2115079/80, 2111951.
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
P.O. Box 2819, DAR ES SALAAM
Tetex House, 4th Floor, Pamba Road

AIP

Supplement 11 – 19/08
20 November 2008

AERODROME (AD)

S11 Julius Nyerere International Airport – HTDA

Aerodrome Controllers' vision from tower is poor for aircraft landing and taking off from runways 05 and 23 due to glass being opaque caused by wearing out. Pilots are to exercise caution, when landing and taking off.

(Cancel NOTAM A/0219/08)

S13 Mbeya – HTMB

Rescue and Fire fighting services not available.

(Cancel NOTAM B0135/08)

S15. Moshi – HTMS

Runway 18/36 closed due to pot holes

(Cancel NOTAM C0199/08)

S16. Same – HTSE

Runway 15/33 closed due to pot holes and ridges

(Cancel NOTAM C0192/08)

S17. Maswa– HTMC

Aerodrome operating, but caution advised due to movement of people and animals along the runway (RWY12/30).

(Cancel NOTAM C0190/08)

S18. Klein's Camp– HTKC

Aerodrome operating, but caution advised due to movement of people and animals along the runway. Aircraft wishing to operate at the aerodrome are required to contact Klein's Camp one day before the operation, on telephone +255 28 2621623.

(Cancel NOTAM C0181/08)

S19 Ukerewe – HTUK

Aerodrome closed.

(Cancel NOTAM C0177/08)
