



FAX: (255 22) 2124914, 2118905  
PHONE: (255 22) 2115079/80, 2111951.  
AFS: HTDQYOYO  
Email: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz), [ais@tcaa.go.tz](mailto:ais@tcaa.go.tz)  
Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA**  
TANZANIA CIVIL AVIATION AUTHORITY  
Aeronautical Information Services  
P.O. Box 2819, DAR ES SALAAM  
Tetex House, 4<sup>th</sup> Floor, Pamba Road

**AIP**  
**Supplement 1-5/2006**

1 January 2006

Document No:  
TCAA/FRM/ANS/AIS-56

Title: **AIP Supplement**

Page 1 of 1

## AERODROME (AD)

### **S5 DAR ES SALAAM FIR - HTDC**

Detailed surveyed geographical co-ordinates in WGS-84 system for aerodrome and en-route air navigation obstacles are available in Appendix A to this supplement.

**(Refer S5/2005)**

### **S10 HANDAJENGA - HTXX**

Handajenga airstrip closed to all air operations due maintenance

**(Refer S16/2005).**

### **S15 URAMBO - HTUR**

Runway 12/30 operating but caution advised due to rough surface 400 meters from threshold runway 12 and also movement of people and animals along the runway.

**(Refer S36/2005).**