

MILITARY ACCIDENTS/INCIDENTS

ACCIDENT INVESTIGATION BRANCH Ministry of Infrastructure Development

	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER AGE & EXPERIENCE	OP ERATOR	CIRCUMSTANCES OF ACCIDENT
1	FT- 5 (JJ - 5) SHENYANG TRAINER	28 JUNE 2010 0710 HRS	MPANGA VILLAGE Near KABUKU, CHALINZE – SEGERA HIGHWAY	CUTHBERT LEGUNA 41 YRS	JW	Aircraft crashed on road whilst conducting a training exercise. Suspect fuel starvation. INJURIES: Fatal 2 Serious 0 None 0
2	AUGUSTA BELL 412 EP JW 9507	9 JUNE 2008 0900 HRS UTC	MATEVES VILLAGE KISONGO WARD ARUSHA	Maj. NYAMWITANGA WAKETE	JW	Main rotor blade collided with a tree in flight [en-route Arusha-Dodoma] INJURIES: Fatal 6 Serious 0 None 6
3	AUGUSTA BELL 412EP JW 9508	6.12. 2007 0735 HRS UTC	LAKE NATRON NORTHERN TANZANIA	Col. SILVANUS MAYENGA 56 YRS	JW	Aircraft collided with water whilst attempting to conduct a low level photographic flight over the lake. Aircraft destroyed. INJURIES: Fatal 0 Serious 0 None
4	SHORTS SD 360 SHERPA JW 9036	1.6. 2007 0915 ?HRS	KIZOTA DODOMA 1025 hrs utc	Col. SILVANUS MAYENGA 55 YRS	JW	Both engines failed during approach to Dodoma airport. Aircraft force landed in a corn field causing the nose landing gear to collapse. INJURIES: Fatal 0 Serious 0 None 12
5	DHC-5 JW 9024	21.5.1994	BUKOBA AIRPORT	CAPT. MLOLELE	JW	Aircraft collided with a house during an attempted overshoot. INJURIES: Fatal 2 Serious ? None ?
6	HS 748	1.7.1985	MBEYA	CAPT. MBISE	JW	Aircraft reported to have crashed shortly after take-off following engine problem. INJURIES: Fatal 4 Serious? None ?
7	HS 748 JW 9010	7.2.1991	DAR ES SALAAM		JW	Aircraft executed wheels –up landing following a technical fault in the landing gear.

						INJURIES: Fatal 0 Serious ? None?
8	HS 748	1980	LAKE MANYARA		JW	Aircraft belly landed following landing gear problem INJURIES: Fatal 0 Serious 0 None 0