



TEL: 255 22 2110223/2 24
FAX: 255 22 2110264
AFTN: HTDAYNYX
E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
Website: <http://www.tcaa.go.tz>

**UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY**

DAILY NOTAM

**AERONAUTICAL INFORMATION SERVICES
P. O. BOX 18001
DAR ES SALAAM**

01 MARCH 2010

**THE FOLLOWING NOTAM SERIES (A) STILL VALID 01 MARCH 2010.
NOTAM NOT INCLUDED HAVE BEEN CANCELLED TIME EXPIRED,
SUPERSEDED BY AIP SUPPLEMENTS OR INCORPORATED IN THE AIP.**

**SERIES A 2010: 0071, 0070, 0069, 0066, 0065, 0064, 0063, 0061, 0060, 0059,
0058, 0057, 0054, 0053, 0052, 0048, 0047, 0046, 0043, 0042,
0041, 0034, 0033, 0032, 0031, 0029, 0028, 0025, 0021, 0012,
AND 0011**

2009: 0428, 0426, 0420 AND 0419.

A0072/10 100301 DAR ES SALAAM FIR HTDC
1003010000/1003312359 EST

CHECKLIST OF NOTAM SERIES A IN FORCE ON MARCH 01 2010

**YEAR 10 = 2010: 0071, 0070, 0069, 0066, 0065, 0064, 0063, 0061,
0060, 0059, 0043, 0042, 0058, 0057, 0054, 0053,
0052, 0048, 0047, 0046, 0041, 0034, 0033, 0032,
0031, 0029, 0028, 0025, 0021, 0012 AND 0011**

YEAR 09 = 0428, 0426, 0420 AND 0419

LATEST PUBLICATIONS:

AIP AMENDMENT	NR 0031/10
AIP SUPPLEMENT	NR 0011/09
AIC	NR 0015/09

A0071/10 100228 ZANZIBAR HTZA
1002280742/1003301530 EST
ZZ 385 KHZ NDB OUT OF SER.

A0070/10 100225 DAR ES SALAAM HTDA
1002251126/1005251530 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS AT APP FREQ 119.6 MHZ
PILOT TO EXER CTN AND REQ TO BE PATIENT.

A0069/10 100225 DAR ES SALAAM HTDA
1002251121/1005251530 EST

AIR TFC CONTROLLERS TRAINING IN PROGRESS AT ACC FREQ 123.3MHZ
PILOTS TO EXER CTN AND REQ TO BE PATIENT.

A0066/10 100223 DAR ES SALAAM HTDA
1002231257/1003311530 EST
TWY 'Z' AVBL TO ARR ACFT WITH WING SPAN FOR ACFT B737 AND BLW.

A0065/10 100223 DAR ES SALAAM HTDA
1002231145/1003311530 EST
TWY 'Y' CLSD DUE WIP

A0064/10 100223 DAR ES SALAAM HTDA
1002231140/1003311530 EST
TWY 'P' CLSD BTN INT WITH GATE D AND GATE E DUE WIP.

A063/10 100223 DAR ES SALAAM HTDA
1002231130/1003311530 EST
TWY 'P' CLSD BTN INT WITH TWY "W" AND TWY "X" DUE WIP.

A0061/10 100223 DAR ES SALAAM FIR
1002230650/1005241530 EST
ILS MONITOR RWY 05 U/S.

A0060/10 100223 DAR ES SALAAM FIR
1002230635/1005241530 EST
DV FREQ 112.7 MHZ DVOR/DME MONITOR OUT OF SER.

A0059/10 100221 ZANZIBAR HTZA
1002211040/1003031530 EST
RWY LIGHTS OUT OF SER.

A0058/10 100217 ZANZIBAR HTZA
1004160400/1004161600 EST
THR RWY 18 DISPLACED BY 2022M DUE WIP. DECLARED DIST
WILL BE AS FLW:-
RWY TORA TODA ASDA LDA
18 1000 1000 1000 1000
REF AIP SUP 11/09 3- C AND D

A0057/10 100217 ZANZIBAR HTZA
1003050400/1004091600 EST
THR RWY 36 DISPLACED BY 2022M EVERY FRI BTN 0400 TO 1600 UTC DUE WIP.
DECLARED DIST WILL BE AS FLW:-
RWY TORA TODA ASDA LDA
36 1000 1000 1000 1000
REF AIP SUP 11/09 3- C AND D

A0054/10 100216 ZANZIBAR HTZA
1002160647/1003161530 EST
THR LIGHTS RWY 36 U/S

A0053/10 100216 ZANZIBAR HTZA
1002160645/1003161530 EST
END LIGHTS RWY 18 U/S

A0052/10 100216 ZANZIBAR HTZA
1002160400/PERM
THE EXTENDED PORTION OF THE RWY 36 WILL BE USABLE, THE LEN
OF RWY WILL BE 3022M. DECLARED DIST WILL BE AS FLW:-
RWY TORA TODA ASDA LDA
18 3022 3472 3082 3022
36 3022 3472 3082 3022
REF AIP HTZA AD 2.13

A0048/10 100215 ZANZIBAR HTZA
1002151215/1004161500 EST
PAPI RWY 36 AVBL ON TEMPO BASIS AWAITING FLT CK.

A0047/10 100215 ZANZIBAR HTZA
1002151140/PERM
WINDSOCK AVBL PSN 300M FM THR RWY 36, 110M TO THE LEFT.

A0046/10 100215 IRINGA HTIR
1002150700/1003171530 EST
NDB IR 397KHZ UNSERVICEABLE

A0043/10 100211 DAR ES SALAAM HTDA
1002110735/1005111530 EST
ILS GP FREQ 329.6 MHZ RWY 05 OUT OF SER.

A0042/10 100211 SONGEA HTSO
1002110606/1005111530 EST
SG 352 KHZ NDB OPR BUT SUBJ INTR. DUE PWR.

A0041/10 100107 MBEYA HTMB
1002101213/1003101530 EST
MB 320KHZ NDB OPR BUT SUBJ PWR INTRP.

A0034/10 100202 MWANZA HTMW
1002021336/1003021500 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS ON TWR FREQ 119.8 MHZ.

PILOTS TO EXER CTN AND REQ TO BE PATIENT.

- A0033/10 100202 MWANZA HTMW
1002020503/1004271530 EST
MZ 115.7 MHZ DVOR INSTL, COMMISSIONED AND FLT CALIBRATED.
FACILITY TO BE USED FOR ENR AND HOMING ONLY UNTL WHEN
NEW PROC PUBLISHED. RANGE AND COORD TO BE NOTIFIED LATER.
REF AIP HTMW AD 2.19
- A0032/10 100202 MWANZA HTMW
1002020446/1004271530 EST
IAP FOR MZ 115.7 VOR CAT A/B/C/D WITHDRAWN UNTIL NEW PROC
PUBLISHED. REF AIP PAGE AD 2.177/178 AND AIP HTMW AD 2.1
- A0029/10 100127 DAR ES SALAAM HTDA
1002010300/1004061530 EST
RWY 14/32 CLOSED.
- A0028/10 100127 DAR ES SALAAM HTDA
1001271129/1004061530 EST
TWY 'Q' CLOSED DUE WIP.
- A0025/10 100127 ZANZIBAR HTZA
1001271050/1003301500 EST
AD OPERATING BUT CTN ADZ ON LDG/TKOF DUE TO CONCENTRATION OF
BIRDS IN THE VICINITY OF AD DLY BTN 0400-1500 UTC
- A0021/10 100122 DAR ES SALAAM HTDA
1001221016/PERM
INTL NOTAM OFFICE ASSIGNED NEW MOBILE PHONE
NR. +255 756 334404
- A0012/10 100115 DAR ES SALAAM HTDA
1001150613/1004141530 EST
ATIS 119.0 MHZ OUT OF SER
- A0011/10 100114 KILIMANJARO HTKJ
1001180500/1004181500 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS ON TWR/APP FREQ
119.9/120.1 MHZ. PILOTS TO EXER CTN AND REQ TO BE PATIENT.
- A0428/09 091227 ZANZIBAR HTZA
0912271229/1008260400 EST
DLY BTN 1600 - 0400UTC
RWY 18/36 CLSD DUE WIP

A0426/09 091227 ZANZIBAR HTZA
0912271200/1003301530 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS ON TWR FREQ 121.2 MHZ.
PILOTS TO EXER CTN AND REQ TO BE PATIENT

A0420/09 091222 ZANZIBAR HTZA
0912220840/1003221530 EST
TWY EDGE LGT TWY A AND B U/S

A0419/09 091222 ZANZIBAR HTZA
0912220800/1003221530 EST
APCH LGT RWY 36 OUT OF SER

THE END