



TEL: 255 22 2110223/2 24
 FAX: 255 22 2110264
 AFTN: HTDAYNYX
 E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
 Website: <http://www.tcaa.go.tz>

**UNITED REPUBLIC OF TANZANIA
 TANZANIA CIVIL AVIATION AUTHORITY**

DAILY NOTAM

AERONAUTICAL INFORMATION SERVICES

**P. O. BOX 18001
 DAR ES SALAAM**

11 MARCH 2010

THE FOLLOWING NOTAM SERIES (A , B & C) WERE STILL VALID ON 11 MARCH 2010

SERIES A 2010: 0083, 0082, 0078, 0077, 0072, 0071, 0070, 0069, 0066, 0065, 0064, 0063, 0061, 0060, 0058, 0054, 0053, 0048, 0047, 0046, 0043, 0042, 0041, 0033, 0032, 0029, 0028, 0025, 0021, 0012 AND 0011

2009: 0428, 0426, 0420 AND 0419.

A0083/10 100303 ZANZIBAR HTZA
 1003120400/1004091600 EST
 THR RWY 36 DISPLACED BY 2022M EVERY FRI BTN 0400 TO 1600 UTC DUE WIP.
 DECLARED DIST WILL BE AS FLW:-

RWY	TORA	TODA	ASDA	LDA
36	1000	1000	1000	1000

 REF AIP SUP 11/09 3- C AND D

A0082/10 100303 ZANZIBAR HTZA
 1003030630/1004061530 EST
 REDL RWY 18/36 OUT OF SER.

A0078/10 100302 ZANZIBAR HTZA
 1003020830/1003311530 EST
 IAP ZV/VOR/DME RWY 36 WITHDRAWN

A/0077/10 100302 ZANZIBAR HTZA
 1003020532/PERM
 THE EXTENDED PORTION OF THE RWY 36 IS USABLE, THE LEN
 OF RWY WILL BE 3022M. DECLARED DIST WILL BE AS FLW:-

RWY	TORA	TODA	ASDA	LDA
18	3022	3472	3082	3022
36	3022	3472	3082	3022

 REF AIP HTZA AD 2.13

A0072/10 100301 DAR ES SALAAM FIR HTDC
 1003010000/1003312359 EST
 CHECKLIST OF NOTAM SERIES A IN FORCE ON MAR. 01 2010
 YEAR 10 =0071,0070,0069,0066,0065,0064,0063,0061,0060,0059,0058,0057,0054,0053,0052,
 0048,0047,0046,0043,0041,0034,0033,0032 0031,0030,0029,0028,0027,0026,0025,0021,
 0020,0012,0011,0010,0007
 YEAR 09 = 0428,0426, 0420, AND 0419

LATEST PUBLICATIONS:

AIP AMENDMENT NR 0031/10
AIP SUPPLEMENT NR 0011/09
AIC NR 003/10

A0071/10 100228 ZANZIBAR HTZA
1002280742/1003301530 EST
ZZ 385 KHZ NDB OUT OF SER.

A0070/10 100225 DAR ES SALAAM HTDA
1002251126/1005251530 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS AT APP FREQ 119.6 MHZ
PILOT TO EXER CTN AND REQ TO BE PATIENT.

A0069/10 100225 DAR ES SALAAM HTDA
1002251121/1005251530 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS AT ACC FREQ 123.3MHZ
PILOTS TO EXER CTN AND REQ TO BE PATIENT.

A0066/10 100223 DAR ES SALAAM HTDA
1002231257/1003311530 EST
TWY 'Z' AVBL TO ARR ACFT WITH WING SPAN FOR ACFT B737 AND BLW.

A0065/10 100223 DAR ES SALAAM HTDA
1002231145/1003311530 EST
TWY 'Y' CLSD DUE WIP

A0064/10 100223 DAR ES SALAAM HTDA
1002231140/1003311530 EST
TWY 'P' CLSD BTN INT WITH GATE D AND GATE E DUE WIP.

A063/10 100223 DAR ES SALAAM HTDA
1002231130/1003311530 EST
TWY 'P' CLSD BTN INT WITH TWY "W" AND TWY "X" DUE WIP.

A0061/10 100223 DAR ES SALAAM FIR
1002230650/1005241530 EST
ILS MONITOR RWY 05 U/S.

A0060/10 100223 DAR ES SALAAM FIR
1002230635/1005241530 EST
DV FREQ 112.7 MHZ DVOR/DME MONITOR OUT OF SER.

A0058/10 100217 ZANZIBAR HTZA
1004160400/1004161600 EST
THR RWY 18 DISPLACED BY 2022M DUE WIP. DECLARED DIST
WILL BE AS FLW:-
RWY TORA TODA ASDA LDA
18 1000 1000 1000 1000
REF AIP SUP 11/09 3- C AND D

A0054/10 100216 ZANZIBAR HTZA
1002160647/1003161530 EST
THR LIGHTS RWY 36 U/S

A0053/10 100216 ZANZIBAR HTZA
1002160645/1003161530 EST
END LIGHTS RWY 18 U/S

A0048/10 100215 ZANZIBAR HTZA
1002151215/1004161500 EST
PAPI RWY 36 AVBL ON TEMPO BASIS AWAITING FLT CK.

A0047/10 100215 ZANZIBAR HTZA
1002151140/PERM
WINDSOCK AVBL PSN 300M FM THR RWY 36, 110M TO THE LEFT.

A0046/10 100215 IRINGA HTIR
1002150700/1003171530 EST
NDB IR 397KHZ UNSERVICEABLE

A0043/10 100211 DAR ES SALAAM HTDA
1002110735/1005111530 EST
ILS GP FREQ 329.6 MHZ RWY 05 OUT OF SER.

A0042/10 100211 SONGEA HTSO
1002110606/1005111530 EST
SG 352 KHZ NDB OPR BUT SUBJ INTR. DUE PWR.

A0041/10 100107 MBEYA HTMB
1002101213/1003101530 EST
MB 320KHZ NDB OPR BUT SUBJ PWR INTRP.

A0033/10 100202 MWANZA HTMW
1002020503/1004271530 EST
MZ 115.7 MHZ DVOR INSTL, COMMISSIONED AND FLT CALIBRATED.
FACILITY TO BE USED FOR ENR AND HOMING ONLY UNTL WHEN
NEW PROC PUBLISHED. RANGE AND COORD TO BE NOTIFIED LATER.
REF AIP HTMW AD 2.19

A0032/10 100202 MWANZA HTMW
1002020446/1004271530 EST
IAP FOR MZ 115.7 VOR CAT A/B/C/D WITHDRAWN UNTIL NEW PROC
PUBLISHED. REF AIP PAGE AD 2.177/178 AND AIP HTMW AD 2.1

A0029/10 100127 DAR ES SALAAM HTDA
1002010300/1004061530 EST
RWY 14/32 CLOSED.

A0028/10 100127 DAR ES SALAAM HTDA
1001271129/1004061530 EST
TWY 'Q' CLOSED DUE WIP.

A0025/10 100127 ZANZIBAR HTZA
1001271050/1003301500 EST
AD OPERATING BUT CTN ADZ ON LDG/TKOF DUE TO CONCENTRATION OF
BIRDS IN THE VICINITY OF AD DLY BTN 0400-1500 UTC

A0021/10 100122 DAR ES SALAAM HTDA
1001221016/PERM
INTL NOTAM OFFICE ASSIGNED NEW MOBILE PHONE
NR. +255 756 334404

A0012/10 100115 DAR ES SALAAM HTDA
1001150613/1004141530 EST
ATIS 119.0 MHZ OUT OF SER

A0011/10 100114 KILIMANJARO HTKJ
1001180500/1004181500 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS ON TWR/APP FREQ
119.9/120.1 MHZ. PILOTS TO EXER CTN AND REQ TO BE PATIENT.

A0428/09 091227 ZANZIBAR HTZA
0912271229/1008260400 EST
DLY BTN 1600 - 0400UTC
RWY 18/36 CLSD DUE WIP

A0426/09 091227 ZANZIBAR HTZA
0912271200/1003301530 EST
AIR TFC CONTROLLERS TRAINING IN PROGRESS ON TWR FREQ 121.2 MHZ.
PILOTS TO EXER CTN AND REQ TO BE PATIENT

A0420/09 091222 ZANZIBAR HTZA
0912220840/1003221530 EST
TWY EDGE LGT TWY A AND B U/S

A0419/09 091222 ZANZIBAR HTZA
0912220800/1003221530 EST
APCH LGT RWY 36 OUT OF SER

SERIES B 2010: 0034, 0032, 0031, 0030, 0029, 0023, 0022, 0021, 0020, AND 0007

B0034/10 100309 MBEYA HTMB
1003090600/1003131530 EST
RWY 13/31 OPR BUT CTN ADVISED ON LDG/TKOF DUE GRASS CUTTING WIP

B0032/10 100303 DODOMA HTDO
1003030540/1004151530 EST
FUEL JET A1 AVAILABLE ONLY FOR SMALL AIRCRAFT BY OVERWING REFUELING
SYSTEM.

B0031/10 100301 TABORA HTTP
1003011018/1004301530 EST
WSPD INDICATOR OUT OF SER

0030/10 100201 DAR ES SALAAM FIR HTDC
1003010000/1003312359 EST
CHECKLIST OF NOTAM SERIES B IN FORCE ON MAR.01 2010

YEAR= 10: 0013, 0014,0020,0021,0022,0023,0029

LATEST PUBLICATIONS:

AIP AMENDMENT	NR 0031/10
AIP SUPPLEMENT	NR 0011/09
AIC	NR 003/10

B0029/10 100223 TABORA HTTP
1002230835/1004301530 EST
RWY 13/31 OPR BUT CTN ADVISED ON LDG/TKOF WHEN WET DUE TO SOFT AND
SLIPPERY SFC.

B0023/10 100215 DODOMA HTDO
1002150920/1005181530 EST
APCH LIGHT RWY 28 U/S

B0022/10 100210 ARUSHA HTAR
1002100840/1004131530 EST
RWY 09/27 OPR BUT CTN ADZ DUE LOOSE CHIPPINGS APRX 1300M FM
THR RWY 09. PILOT TO EXER CTN ON LDG/TKOF.

B0021/10 100210 ARUSHA HTAR
1002100830/1004131530 EST
RWY 09/27 OPR BUT CTN DUE NIL RWY MARKING 1200M FROM THR RWY 09.

B0020/10 100208 MTWARA HTMT
1002081158/1004081530 EST
ATC OBSTRUCTED OF VISION FM CTL PSN FOR AD TRAFFIC OPR ON THE
LATE LEFT DOWNWIND AND LEFT BASE RWY 19. PILOTS TO REPORT PSN AND
STRICTLY ADHERE TO ATC INSTRUCTIONS WHEN POSITIONING ON LEFT
DOWNWIND AND LEFT BASE RWY 19.

B0007/10 100122 MTWARA HTMT
1001220855/1003231530 EST
RWY 01/19 OPR BUT CTN ADVISED DUE TO WIP. OUTSIDE HR OF SKED
OPS FOR NON - SKED HRS PN BFR OPR (REF AIP HTMT 2.3)

SERIES C 2010: 0030, 0028, 0025, 0024, 0021, 0004 AND 0003

C0030/10 100310 BUKOBA HTBU
1003100959/1003171530 EST
RWY 13/31 CLSD DUE WIP.

C0028/10 100303 MASWA HTMC
1003030536/1004061530 EST
WIND SOCK NOT AVBL.

C0025/10 100301 DAR ES SALAAM FIR HTDC
1003010000/1003312359 EST
CHECKLIST OF NOTAM SERIES C IN FORCE ON MAR 01 2010
YEAR 10 = 0024, 0023, 0021, 0017, 0016, 0004 AND 0003,

LATEST PUBLICATIONS:

AIP AMENDMENT	NR 0031/10
AIP SUPPLEMENT	NR 0011/09
AIC	NR 003/10

C00024/10 100225 SHINYANGA HTSY
1003010400/1003151530 EST
RWY 11/29 CLSD DUE WIP.

C0021/10 100211TUNDURU HTTU
1002110622/1003111530 EST
RWY 11/29 CLSD DUE POTHOLES ON THE RWY CENTERLINE.

C0004/10 100105 KONGWA HTKO
1001051605/1004301530 EST
RWY 12/30 CLSD DUE SWAMPING.
REF AIP HTKO AD 2.12.

C0003/10 100105 KILOSA HTKS
1001051544/1004301530 EST
RWY 10/28 CLSD DUE SWAMPING.

THE END

