

 <p><b>FAX:</b> (255 22) 2844300, 2844302  <b>PHONE:</b> (255 22) 2198100  <b>AFS:</b> HTDQYOYO  <b>Email:</b> <a href="mailto:tcaa@tcaa.go.tz">tcaa@tcaa.go.tz</a>, <a href="mailto:ais@tcaa.go.tz">ais@tcaa.go.tz</a>  <b>Website:</b> <a href="http://www.tcaa.go.tz">www.tcaa.go.tz</a></p>	<p align="center"><b>UNITED REPUBLIC OF TANZANIA</b>  <b>TANZANIA CIVIL AVIATION AUTHORITY</b>  Aeronautical Information Management  Nyerere/ Kitunda Road Junction  Aviation House, 1st Floor,  P.O. Box 2819, DAR ES SALAAM</p>	<p align="center"><b>AIP</b>  <b>Supplement</b>    <b>15/20</b>    <b>01 July 2020</b></p>
<p><b>Document No:</b>  <b>TCAA/FRM/ANS/AIS - 56</b></p>	<p align="center"><b>Title: AIP Supplement</b></p>	<p align="center"><b>Page 1 of 1</b></p>

### AERODROMES (AD)

#### S15 Moshi Airport - HTMS

The following Obstacles have been reported to be around Moshi Airport, Pilots are advised to exercise caution during Landing or Take-off RWY 08/26.

#### OBSTACLES AROUND MOSHI AIRPORT

S/N	TYPE	SITE ID	OBSTACLE POSITION	HEIGHT (M)	ELEV (M)	AFFECTED RWY	DISTANCE FROM THR (M)	OLS PENETRATION
1.	AERIAL MAST	MOSHI CENTRAL CENTRAL ROOM#: 3009	03° 21' 26.6" S 037° 20' 14.9"E	45	890	26	711	APPROACH + INNER HORIZONTAL SURFACES
2.	AERIAL MAST	KIL 0103	03° 21' 49.4"S 037° 20' 10.7"E	49.5	874.5	26	498	APPROACH + INNER HORIZONTAL SURFACES
3.	AERIAL MAST	TZ 1080	03° 21' 46.0" S 037° 20' 17.0"E	45	864	26	639	APPROACH + INNER HORIZONTAL SURFACES
4.	AERIAL MAST	KIUSA MOSHI 096	03° 21' 16.8" S 037° 19' 52.2" E	45	897	26	764	TRANSITIONAL SURFACE
5.	AERIAL MAST	SOWETO 3K 1004	03° 22' 05.3" S 037° 19' 14.7" E	49.5	880.5	08	516	TRANSITIONAL + INNER HORIZONTAL SURFACE