



FAX: (255 22) 2844300, 2844302
PHONE: (255 22) 2198100
AFS: HTDQYOYO
Email: tcaa@tcaa.go.tz, ais@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Services
Nyerere /Kitunda Road Junction
Aviation House, 1st Floor,
P.O. Box 2819, DAR ES SALAAM

AIP
Supplement
16 - 18/15
08 January 2015

Document No:
TCAA/FRM/ANS/AIS-56

Title: AIP Supplement

Page 1 of 1

AERODROMES (AD)

- S16 Tunduru – HTTU**
Runway 11/29 closed due potholes on the runway center line.
(Replace AIP SUP S10/12)
- S18 Ukerewe – HTUK**
Aerodrome closed.
(Replace AIP SUP S19/08)