

## 1999 AIR ACCIDENTS

# MINISTRY OF COMMUNICATION AND TRANSPORT

## TANZANIA ACCIDENT INVESTIGATION BRANCH

NO	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER AGE & EXPERIENCE	OPERATOR	TYPE OF ACCIDENT
1	PIPER PA 34 – 20 5H – ZAB	24.01.99 08:47 HRS	ZANZIBAR AIRPORT	J. B. LILLA 35 YRS. 2900 HRS	ZANAIR	NOSE LDG GEAR FAILED TO EXTEND A/C LANDED ON NOSE & MAINS  INJURIES : FATAL 0 SERIOUS 0 NONE 6
2	CESSNA 182 5H – COF	24.03.99 08:50 HRS	ARUSHA AIRPORT	FRANCIS MAHUNDI 26 YRS. 150 HRS	TANZANIA NATIONAL PARKS	A/C SWERVED OFF THE RUNWAY ON LANDING  INJURIES : FATAL 0 SERIOUS 0 NONE 4
3	CESSNA 206 ZS – DIT	11.04.99 05:30 HRS	CHUNYA AIRSTRIP	RICHARD NEZAR	MEREMETA CO. MWANZA	NOSE LDG GEAR SUNK INTO SOFT GROUND, PROPELLER STRIKE  INJURIES : FATAL 0 SERIOUS 0 NONE 1
4	CESSNA 404 5Y – LEA	23.04.99	KILOMBERO AIRSTRIP	DONALD V. D.'Sa	LONRHO MOTORS (EA) LTD. NAIROBI	WHILST LINING UP FOR TAKE OFF LEFT MAIN LDG GEAR SUNK IN SOFT GROUND, PROPELLER STRIKE  INJURIES : FATAL 0 SERIOUS 0 NONE 5
5	BOEING 737 – 200 5H – MRK	26.05.99 05:31 HRS	ENROUTE DAR/MWANZA	M. J. MNYUNE 45 YRS. 11,000 HRS	AIR TANZANIA	ENGINE FAILURE IN AIR DUE TO FRACTURE OF GEARBOX BEVEL DRIVE GEAR. MASSIVE FUEL SPILLAGE.  INJURIES : FATAL 0 SERIOUS 0 NONE 70
6	BOEING 767 – 200 ZS – SRB	18.06.99 08:33 HRS	DAR INTERNATIONAL	CAPT. R. LUCICE 50 YRS. 16,000 HRS	SOUTH AFRICAN AIRWAYS/ALLIANCE AIR	A/C ABORTED TAKE-OFF AFTER V <sub>1</sub> WHEN A BIRD WAS INGESTED IN NO. 1 ENGINE.  INJURIES : FATAL 0 SERIOUS 0 NONE 138
7	CESSNA 185 5H – PVT	07.07.99 13:02 HRS	ARUSHA AIRPORT	ARNOLD EKKO 33 YRS. 800 HRS	POP VRIEND ARUSHA	PROPELLER STRUCK A PARKED CAR WHILST TAXYING TO HANGAR  INJURIES : FATAL 0 SERIOUS 0 NONE 1
8	CESSNA 404 5H – RAY	14.07.99 06:45 HRS	ENGASSUMET ARUSHA	ANTHONY S. ILES 26 YRS. 2,500 HRS	FLEET AIR	LEFT MAIN LDG GEAR SEPARATED DURING LDG ROLL. A/C GROUND LOOPED.  INJURIES : FATAL 0 SERIOUS 0 NONE 6
9	CESSNA 152 ZS – NFD	14.07.99 09:47 HRS	MTOKELA, RUNGWE MBEYA	BEULER PERCEVAL 25 YRS. 800 HRS	99' FLYING CLUB	AIR FORCE-LANDED ON TARMAC ROAD DUE TO LOW FUEL.  INJURIES : FATAL 0 SERIOUS 0 NONE 1
10	LET 410 UVP – E9 5H – PAB	26.07.99 13:10 HRS	ARUSHA AIRPORT	O. A. MOSHA 42 YRS. 12,000 HRS	PRECISIONAIR	A/C EXECUTED WHEELS UP LANDING ON TRAINING FLIGHT.  INJURIES : FATAL 0 SERIOUS 0 NONE 4

NO	TYPE & REG.	DATE & TIME UTC	LOCATION	COMMANDER AGE & EXPERIENCE	OPERATOR	TYPE OF ACCIDENT
11	PIPER PA 34 – 200T  5H – ZAB	29.07.99  13:17 HRS	ZANZIBAR AIRPORT	P. S. MSIKINYA 44 YRS. 13,000 HRS	ZANAIR	RIGHT MAIN LDG GEAR DISLOCATED DURING LDG ROLL.  INJURIES : FATAL 0 SERIOUS 0 NONE 5
12	CESSNA 404  5H – NAT	01.09.99  07:20 HRS	SOUTHERN SLOPE OF MT. MERU	CHRIS PEREIRA 39 YRS. 16,500 HRS	NORTHERN AIR	A/C COLLIDED WITH HIGH GROUND IN BAD WEATHER  INJURIES : FATAL 12 SERIOUS 0 NONE 0
13	CESSNA 406  5H – TZC	03.09.99  07:42 HRS	MKUYU AIRSTRIP SELOUS	C. MUTAYOBA 45 YRS 7,500 HRS	TANZANAIR	A/C COLLIDED WITH 13 VULTURES SHORTLY AFTER TAKE-OFF, A/C EXTENSIVELY DAMAGED.  INJURIES : FATAL 0 SERIOUS 0 NONE 1
14	CESSNA 208  7Q - YKR	21.09.99 09:10 HRS	MBEYA AIRPORT	CAPT. PHAKAMEA	AIR MALAWI	A/C TYRE BURST ON LANDING.  INJURIES : FATAL 0 SERIOUS 0 NONE 4
15	BOEING 737 – 200 5H – MRK	31.10.99  09:10 HRS	KILIMANJARO AIRPORT	M. J. MNYUNE 45 YRS. 11,000 HRS	AIR TANZANIA	A/C ABORTED TAKE-OFF FOLLOWING FAILURE OF NO. 2 MAIN WHEEL TYRE. ALL THREE OTHER TYRES DEFLATED. EMERGENCY EVACUATION ORDERED.  INJURIES : FATAL 0 SERIOUS 2 NONE 80
16	MISSIONAIR GOOD NEWS EXP. MICROLIGHT 5H – MGN	5.11.99  16:00 HRS	ITIGI AIRSTRIP MANYONI DISTRICT	DAVID FINKE 31 YRS. 400 HRS	WORLD OUTREACH DODOMA	RIGHT MAIN LDG GEAR STUCK IN A HOLE ON RWY DURING TAKE OFF ROLL. A/C GROUND LOOPED. PROP STRIKE.  INJURIES : FATAL 0 SERIOUS 0 NONE 3
17	CAMERON A 315 BALLOON  5H – IPO	28.11.99  05:15 HRS	SERONERA SERENGETI	ROSS POWELL 50 YRS. 1,360 HRS	SERENGETI BALLOON SAFARIS	BALLOON COLLIDED WITH A TREE SHORTLY BEFORE TOUCH DOWN.  INJURIES : FATAL 0 SERIOUS 2 NONE 8
18	PIPER PA 32 – 300  5H – MTU	11.12.99  09:19 HRS	AMANI GOMVU AIRSTRIP 30 MILES SOUTH OF DAR ES SALAAM	W. HERING 58 YRS. 1,300 HRS	W. HERING	A/C COLLIDED WITH A TREE DURING A FORCED LANDING FOLLOWING ENGINE FAILURE.  INJURIES : FATAL 0 SERIOUS 0 NONE 1
19	CESSNA 402  5H – GTO	13.12.99  12:38 HRS	CHANKONDE AIRSTRIP MBEYA	M. AMIN 42 YRS. 2,700 HRS	TWIN WINGS ZANZIBAR	A/C OVERRAN RWY DURING ABORTED TAKE-OFF, A/C COLLIDED WITH TREES. BOTH WINGS TORN OFF.  INJURIES : FATAL 0 SERIOUS 1 NONE 5

**GLOSSARY:** A/C : Aircraft                      LDG : Landing                      RWY : Runway                      T/O : Take-off                      UTC : Universal Time Co-ordinated

LIGHT SHADING indicates aircraft completely destroyed or extensively damaged.  
DARK SHADING indicates fatal accident