



TEL: 255 22 2110223/224
 FAX: 255 22 2110264
 AFTN: HTDAYNYX
 E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
 Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
 Aeronautical Information Management
 International NOTAM Office
 P. O. Box 18001,
 DAR ES SALAAM
 TANZANIA

MONTHLY NOTAM

LIST

Series A

01 FEBRUARY 2018

Document No: TCAA/FRM/ANS/AIM-33	Title: Daily List of Valid NOTAM	Page 1 of 8
--	---	--------------------

THE FOLLOWING NOTAM SERIES A WERE STILL VALID ON 01 FEBRUARY 2018 NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP.

SERIES: A	<p>2018: 0028, 0025, 0024, 0023, 0021, 0020, 0007, 0006, 0005. 2017: 0375, 0360, 0355, 0347, 0346, 0342, 0341, 0340, 0339, 0327 AND 0060</p>
A0028/18	<p>1801201 DAR ES SALAAM FIR HTDC 1802010000/1802282359 EST CHECKLIST OF NOTAM SERIES A IN FORCE ON FEB. 1 2018 YEAR=17 0060 0327 0339 0340 0341 0342 0346 0347 0355 0360 0375 YEAR=18 0005 0006 0007 0020 0021 0023 0024 0025</p> <p>LATEST PUBLICATIONS: AIP AMENDMENT NR 0063/18 AIP SUPPLEMENT NR 0002/18 AIC NR 0005/18</p> <p>CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 AND 10 2015: 3 AND 5 2017: 4 5 6 8 9 10 11 AND 12 2018: 1 2 3 4 AND 5</p>

	<p>CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 6 7 8 9 12 16 17 AND 18 2016: 4 9 15 16 AND 18 2017: 2 3 14 AND 17 2018: 1 AND 2</p>
A0025/18	<p>180131 DAR ES SALAAM FIR HTDC 1801310844/1804201530 EST PSR U/S.</p>
A0024/18	<p>180130 JULIUS NYERERE INTL AIRPORT HTDA 1801301230/1803301530 EST PORTION OF TWY 'P' FM GATE 'E' TO INT OF RWY 23 CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.</p>
A0023/18	<p>180130 JULIUS NYERERE INTL AIRPORT HTDA 1801301230/1803301530 EST GATE 'E' CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.</p>
A0021/18	<p>180129 KILIMANJARO INTL AIRPORT HTKJ 1801290840/1802281530 EST ATIS U/S.</p>
A0020/18	<p>180129 DODOMA HTDO 1801290830/1802121530 EST DO 373 KHZ NDB U/S.</p>
A0007/18	<p>180105 MWANZA HTMW 1801070430/1804051630 EST DLY 0430-1630 RWY 12/30 OPR BUT CTN ADVISED DUE CONST OF NEW CARGO APN TWY WIP WITHIN THE STRIP AT THE THR OF RWY 12 (NORTHWEST SIDE). PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.</p>
A0006/18	<p>180105 DAR ES SALAAM FIR HTDC 1801051405/1802281430 JAN 05 - FEB 28 (0500 - 1430). DRONE FLIGHTS OPS WILL TAKE PLACE AT KUNDUCHI AREA (DAR ES SALAAM) COORD: 064208.04S 0391332.30E CENTRED WI RADIUS OF 6.25NM. PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. OPS SUBJ CHANGE DUE WX. FM GND TO 3000FT.</p>
A0005/18	<p>180104 DAR ES SALAAM FIR HTDC 1801041510/1802012359 EST NIL AIRAC PUBLICATION EFFECTIVE DATE 01 FEB 2018. (REF: AIP GEN 3.1-4).</p>
A0375/17	<p>171229 ZANZIBAR INTL AIRPORT HTZA 1712290617/1803291530 EST ZZ 385 KHZ NDB U/S.</p>

A0360/17	171214 JULIUS NYERERE INTL AIRPORT HTDA 1712141015/1803301530 EST AWOS (AUTOMATIC WEATHER OBSERVING SYSTEM) U/S.
A0355/17	171211 MWANZA HTMW 1712111530/1802111530 EST APCH LGT RWY 30 REMOVED DUE EXCAVATION AND BACKFILLING WIP ON THE EXTENDED PART OF RWY 30.
A0347/17	171205 MWANZA HTMW 1712061530/1803061530 EST RWY END LGT RWY 12 TEMPO SHIFTED BY 30M INWARD FM THE BEGINNING OF RWY 30 DUE WIP. (REF: AIP HTMW AD 2.14).
A0346/17	171205 MWANZA HTMW 1712051554/1803061530 EST THR RWY 30 DISPLACED BY 300M DUE WIP. DECLARED DIST TO READ AS FLWS.: RWY TORA TODA ASDA LDA 12 3270M 3270M 3270M 3108M 30 3270M 3270M 3270M 3000M (REF: AIP HTMW AD 2.13).
A0342/17	171205 DAR ES SALAAM FIR HTDC 1712050500/1803051300 EST DLY 0500-1300 DANGER AREA HTD9, HTD10 AND HTD11 ACTIVATED (REF AIP ENR 5.1-3) FM GND TO 20000FT.
A0341/17	171205 DAR ES SALAAM FIR HTDC 1712050500/1803051300 EST DLY 0500-1300 MIL TRAINING FLT WILL TAKE PLACE FM HTMW COORD 022638S 0325554E TO THE AREA HTD9, HTD10, HTD11 AND BACK TO HTMW, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS, FM GND TO 10000FT.
A0340/17	171205 DAR ES SALAAM FIR HTDC 1712050400/1803051300 EST DLY 0400 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM TANGA WI AN AREA ENCLOSED WITH THE FOLLOWING COORD:- 05 02 24.705S 038 59 05.881E 04 56 35.986S 038 48 33.782E 05 22 27.105S 038 58 33.955E 05 11 02.295S 039 02 26.620E, PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. CIVILIAN OPS AT HTTG COMMENCE AT NML TIME 0430 UTC, FM GND TO 6000FT.
A0339/17	171205 DAR ES SALAAM FIR HTDC 1712050500/1803051300 EST MON – FRI 0500 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM HTDA COORD 065241S 0391209E TO HTNG COORD 0643S 03808E AND BACK TO HTDA, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS,

	FM 1500FT TO 7000FT.
A0327/17	171115 ARUSHA HTAR 1711151520/1802141530 EST AR 391 KHZ NDB TEMPO WITHDRAWN. (REF: AIP HTAR AD 2.19).
A0060/17	170321 JULIUS NYERERE INTL AIRPORT HTDA 1703210712/ PERM DUE TO APN LAYOUT CHANGES FM ORIGINAL APN LAYOUT ON AEROBRIDGES D1, D2, E1, E2 AND E3, PILOTS ADVISED TO FLW MARSHALLER'S INSTRUCTIONS.

LATEST PUBLICATIONS:

AIP AMENDMENT NR 0063/18
AIP SUPPLEMENT NR 0002/18
AIC NR 0005/18

CHECKLIST OF VALID AICS:

YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43
46 47 51 53 55 AND 56
2001: 3
2002: 2 AND 4
2003: 3 7 8 13 AND 14
2004: 5 AND 8
2005: 4 AND 12
2006: 8 9 AND 10
2007: 8
2008: 3 6 8 AND 10
2009: 4 7 8 10 12 13 AND 14
2010: 3 AND 4
2011: 3 4 AND 5
2012: 10 AND 11
2013: 3 7 AND 9
2014: 3 4 AND 10
2015: 3 AND 5
2017: 4 5 6 8 9 10 11 AND 12
2018: 1 2 3 4 AND 5

CHECKLIST OF VALID AIP SUPPLEMENTS:

YEAR 2006: 5 AND 15
2007: 13
2009: 10
2010: 20
2013: 11 AND 13
2014: 2 AND 4
2015: 6 7 8 9 12 16 17 AND 18
2016: 4 9 15 16 AND 18
2017: 2 3 14 AND 17
2018: 2 AND 3

***** END *****