



TEL: 255 22 2110223/224
 FAX: 255 22 2110264
 AFTN: HTDAYNYX
 E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
 Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
 Aeronautical Information Management
 International NOTAM Office
 P. O. Box 18001,
 DAR ES SALAAM
 TANZANIA

MONTHLY NOTAM

LIST

Series A

01 JANUARY 2019

Document No:
TCAA/FRM/ANS/AIM-32

Title: Monthly List of Valid NOTAM

Page 1 of 4

THE FOLLOWING NOTAM SERIES A WERE STILL VALID ON 01 JANUARY 2019 NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP.

SERIES: A	2019: 0001 2018: 0442, 0441, 0438, 0437, 0435, 0434, 0433, 0431, 0424, 0420, 0414, 0413, 0411 0410, 0409, 0408, 0405, 0397, 0396, 0395, 0357, 0353, 0341, 0339 AND 0338
A0001/19	190101 DAR ES SALAAM FIR HTDC 1901010000/1901312359 EST NOTAM CHECKLIST
A0442/18	181231 MWANZA AIRPORT HTMW 1812311330/1903291530 EST FIRE FIGHTING AND RESCUE SER CHANGED TO CAT 8. (REF: AIP HTMW AD 2.6)
A0441/18	181229 MWANZA AIRPORT HTMW 1812310300/1903291530 EST DAILY 0300-1530 TURNING AREA HAS BEEN ESTABLISHED AT THE END OF RWY 12 WITH A LEN OF 500M.
A0438/18	181228 DAR ES SALAAM FIR HTDC 1812281036/1903281530 EST ZZ 385 KHZ NDB U/S.
A0437	181228 DAR ES SALAAM FIR HTDC 1812281036/1903281530 EST ZZ 385 KHZ NDB U/S.
A0435/18	181227 ABEID AMANI KARUME INTL AIRPORT HTZA 1812271351/1901211530 EST TWR SGL LAMP U/S.
A0434/18	181227 DAR ES SALAAM FIR HTDC 1812272300/1901030200 EST 2300-0200 EXPECTING VOICE COM (ATS-DS AND VHF) INTRP DUE REHABILITATION WIP AT ACC AND EQPT ROOM, PILOTS TO CALL ON HF RADIO FREQ (11300KHZ OR 8879KHZ) WHEN NIL COM ON VHF FREQ 123.3MHZ .

A0433/18	181227 DAR ES SALAAM FIR HTDC 1812270500/1903051300 EST MON – FRI 0500 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM HTDA COORD 065241S 0391209E TO HTNG COORD 0643S 03808E AND BACK TO HTDA, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. FM 1500FT AGL TO 7000FT
A0431/18	181227 DAR ES SALAAM FIR HTDC 1812270959/1901031530 SUP 16/18 CNL AS INFO INCORPORATED INTO AIP AMDT NR 66/18.
A0424/18	181221 JULIUS NYERERE INTL AIRPORT HTDA 1812210620/1901211530 EST HTDA/HKNA AND HTDA/FAOR CIRCUITS ARE STILL USING AFTN SYSTEM.
A0420/18	181211 MWANZA AIRPORT HTMW 1812111439/1903111530 EST THR RWY 12 DISPLACED BY 300M DUE WIP. DECLARED DIST TO READ AS FLWS.: RWY TORA TODA ASDA LDA 12 2900M 2900M 2900M 2700M 30 2900M 2900M 2900M 2700M (REF: AIP HTMW AD 2.13).
A0414/18	181210 DAR ES SALAAM FIR HTDC 1812100820/1901101530 EST NDB MT 336 KHZ U/S.
A0413/18	181206 DAR ES SALAAM FIR HTDC 1812060807/1901031530 EST NIL AIRAC PUBLICATION EFFECTIVE DATE 03 JAN 2019.
A0411/18	181205 DAR ES SALAAM FIR HTDC 1812050500/1903051300 EST DLY 0500-1300 DANGER AREA HTD9, HTD10 AND HTD11 ACTIVATED (REF AIP ENR 5.1-3) FM GND TO 20000FT.
A0410/18	181205 DAR ES SALAAM FIR HTDC 1812050500/1903051300 EST DLY 0500-1300 MIL TRAINING FLT WILL TAKE PLACE FM HTMW COORD 022638S 0325554E TO THE AREA HTD9, HTD10, HTD11 AND BACK TO HTMW, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. FM GND TO 10000FT.
A0409/18	181205 DAR ES SALAAM FIR HTDC 1812050400/1903051300 EST DLY 0400 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM TANGA WI AN AREA ENCLOSED WITH THE FOLLOWING COORD:- 05 02 24.705S 038 59 05.881E 04 56 35.986S 038 48 33.782E 05 22 27.105S 038 58 33.955E 05 11 02.295S 039 02 26.620E, PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. CIVILIAN OPS AT HTTG COMMENCE AT NML TIME 0430 UTC, FM GND TO 6000FT.

A0408/18	181205 DAR ES SALAAM FIR HTDC 1812051008/1901051000 EST KL 383 KHZ NDB U/S.
A0405/18	181130 KILIMANJARO INTL AIRPORT HTKJ 1811301110/1902281530 EST ATIS U/S.
A0397/18	181118 MWANZA AIRPORT HTMW 1811180430/1902151530 EST APCH LGT SYSTEM RWY 30 COMPLETELY WITHDRAWN DUE WIP.
A0396/18	181116 KILIMANJARO INTL AIRPORT HTKJ 1811161415/1902151530 EST THR LGT RWY 27 U/S.
A0395/18	181116 KILIMANJARO INTL AIRPORT HTKJ 1811161415/1902151530 EST APPROACH LGT RWY 27 U/S.
A0357/18	181020 DAR ES SALAAM FIR HTDC 1810200933/1901211530 EST PSR U/S.
A0353/18	180717 JULIUS NYERERE INTL AIRPORT HTDA 1810170658/1901171530 EST THR RWY 32 OPR BUT CTN ADVISED DUE DAY AND NIGHT WIP ABOUT 300M ABEAM THR
A0341/18	181005 MWANZA AIRPORT HTMW 1810050430/1901051630 EST DLY 0430-1630 RWY 12/30 OPR BUT CTN ADVISED DUE CONST OF NEW CARGO APN TWY WIP WITHIN THE STRIP AT THE THR OF RWY 12 (NORTH/WEST SIDE). PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0339/18	181003 JULIUS NYERERE INTL AIRPORT HTDA 1810030756/1901031530 EST GP ILS RWY 05 FREQ 329.6 MHZ OPR ON SINGLE SYSTEM ONLY.
A0338/18	181002 DAR ES SALAAM FIR HTDC 1810021100/1901041530 EST AR 391 KHZ NDB TEMPO WITHDRAWN. (REF: AIP HTAR AD 2.19).

LATEST PUBLICATIONS:

AIP AMENDMENT NR 0066/18
AIP SUPPLEMENT NR 0025/18
AIC NR 0008/18

CHECKLIST OF VALID AICS:

**YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43
46 47 51 53 55 AND 56**
2001: 3
2002: 2 AND 4
2003: 3 7 8 13 AND 14
2004: 5 AND 8
2005: 4 AND 12
2006: 8 9 AND 10

2007: 8
2008: 3 6 8 AND 10
2009: 4 7 8 10 12 13 AND 14
2010: 3 AND 4
2011: 3 4 AND 5
2012: 10 AND 11
2013: 3 7 AND 9
2014: 3 4 AND 10
2015: 5
2017: 4 6 8 9 10 11 AND 12
2018: 3 4 5 7 AND 8
2019: 1 AND 2

CHECKLIST OF VALID AIP SUPPLEMENTS:

YEAR 2006: 15
2007: 13
2010: 20
2013: 11 AND 13
2014: 2 AND 4
2015: 7 8 9 12 16 17 AND 18
2016: 4 9 15 AND 16
2017: 3 AND 17
2018: 9 11 22 AND 23
2019: 1 AND 2

***** END *****