



TEL: 255 22 2110223/224
FAX: 255 22 2110264
AFTN: HTDAYNYX
E-mail: tcaa.dia@tcaa.go.tz
nofdia@tcaa.go.tz
Website: www.tcaa.go.tz

UNITED REPUBLIC OF TANZANIA
TANZANIA CIVIL AVIATION AUTHORITY
Aeronautical Information Management
International NOTAM Office
P. O. Box 18001,
DAR ES SALAAM
TANZANIA

DAILY NOTAM

UPDATE

09 NOV 2018

Document No:
TCAA/FRM/ANS/AIM-33

Title: Daily List of Valid NOTAM

Page 1 of 8

THE FOLLOWING NOTAM SERIES (A, B & C) WERE STILL VALID AT 0001 UTC.

SERIES: A	2018: 0379, 0377, 0375, 0374, 0369, 0368, 0367, 0365, 0359, 0357, 0354, 0353, 0351, 0346, 0341, 0339, 0338, 0337, 0335, 0334, 0333, 0318, 0306, 0303, 0302, 0301, 0300, 0295 0280, 0279 AND 0275
A0379/18	181108 DAR ES SALAAM HTDC 1811081544/1812061530 EST NIL AIRAC PUBLICATION EFFECTIVE DATE 06 DEC 2018. (REF:AIP GEN 3.1-4)
A0377/18	181108 DAR ES SALAAM HTDC 1811080300/1811161500 MIL. EXER WILL TAKE PLACE AT TANGA WI THE AREA BOUNDED BY THE FLW COORD: 044500S 0383000E 044500S 0391500E 053000S 0391500E 053000S 0383000E PILOTS TO EXER CTN AND ADHERE TO ATC INSTRUTIONS GND TO 1500FT
A0375/18	181108 MWANZA HTMW 1811080539/1811151530 EST DVOR MV115.7MHZ U/S
A0374/18	181107 MWANZA HTMW 1811070817/1811110500 EST LOW RWY LIGHTS INTST DUE TECHNICAL FAULT IN THE CONSTANT CURRENT REGULATOR SYSTEM
A0369/18	181101 DAR ES SALAAM HTDA 1811012100/1811140200 EST DLY 2100-0200 REPAINTING ON RWY 05/23 INPR, PILOTS STRICTLY ADHERE TO ATC INSTRUCTION.
A0368/18	181101 DAR ES SALAAM HTDA 1811012100/1811140200 EST DLY 2100-0200 REPAINTING ON TWY Z, X, W, Q, V, U AND P INPR, PILOTS STRICTLY ADHERE TO ATC INSTRUCTION.
A0367/18	181101 DAR ES SALAAM HTDA 1811012100/1811140200 EST DLY 2100-0200 REPAINTING ON RWY 14/32 INPR, PILOTS STRICTLY ADHERE TO ATC INSTRUCTION.

This is a controlled Document

A0365/18	<p>181101 DAR ES SALAAM FIR HTDC 1811010000/1811302359 EST CHECKLIST OF NOTAM SERIES A IN FORCE ON NOVEMBER. 01 2018 YEAR=18 0275 0279 0280 0295 0300 0301 0302 0303 0306 0318 0333 0334 0335 0337 0338 0339 0341 0346 0351 0353 0354 0357 0359</p> <p>LATEST PUBLICATIONS: AIP AMENDMENT NR 0065/18 AIP SUPPLEMENT NR 0021/18 AIC NR 0008/18</p> <p>CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 AND 10 2015: 5 2017: 4 6 8 9 10 11 AND 12 2018: 1 2 3 4 5 7 AND 8</p> <p>CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 7 8 9 12 16 17 AND 18 2016: 4 9 15 AND 16 2017: 3 AND 17 2018: 9 11 16 17 19 AND 21</p>
A0359/18	<p>181025 DAR ES SALAAM FIR HTDC 1810261300/1811251500 DAILY 1300-1500 DRONE FLT OPS WILL TAKE PLACE WI THE SINGITA GRUMETI RESERVE BDRY. LAUNCH AND RECOVERY FM SASAKWA AIRSTRIP. PILOTS TO EXER CTN. FM GND TO 1000FT.</p>
A0357/18	<p>181020 DAR ES SALAAM FIR HTDC 1810200933/1901211530 EST PSR U/S.</p>

A0354/18	181016 DAR ES SALAAM FIR HTDC 1810161500/ PERM HAND AMDT ON AIRAC AIP SUP 16/18 EFFECTIVE 11 OCTOBER 2018 AS FLW:- 1. REPLACE AMKIT WITH AKMIT. 2. DELETE THE ROW STARTING WITH ETKOP. 3. AMEND OKTEX COORD TO 010000S 0311409E. 4. REPLACE THE 5LNC DUTGA WITH ANVUN. 5. ETMIS REPLACING DIGSA INSTEAD OF DIGNA ON UT913. 6. ADD NEW ROWS FOR : I) UNGAN 020909.11S 0360602.93E REPLACING ETKOP. HTKJ GNSS WPT. II) UVBOX 035706.92S 0361755.28E REPLACING ARIKI ON UT912/UA401. III) UVKOD 014413.43S 0322052.57E REPLACING VOSLA ON UT910/UL442. IV) UVLED 022227.51S 0321908.63E REPLACING DIMVA ON UT910/UB531. V) UVMAN 050545.36S 0321035.14E REPLACING VOTAB ON UT910. VI) UVMEX 064321.82S 0395451.90E REPLACING AMRES ON UT914. VII) UVMID 033452.41S 0321519.95E REPLACING EBNOS ON UR784/UT910. VIII) UVUMI 053939.42S 0355049.06E REPLACING ARIDO ON UT912/V282. 7. THE WORDS DUMTO AND UNVIL TO BE REPLACED BY DUTMO AND UMVIL RESPECTIVELY. 8. DELETE THE ENTIRE ROW STARTING WITH CODE EROPA. (REFER AIP SUP 16/18)
A0353/18	180717 DAR ES SALAAM INTL AIRPORT HTDA 1810170658/1901171530 EST THR RWY 32 OPR BUT CTN ADVISED DUE DAY AND NIGHT WIP ABOUT 300M ABEAM THR.
A0351/18	181015 JULIUS NYERERE INTL AIRPORT HTDA 1810151035/1811141530 EST HTDA/HKNA AND HTDA/FAOR CIRCUITS WILL BE SWITCHED FM AFTN TO AMHS SWITCH. USERS TO EXP INTERMITTENT COM FOR BOTH INCOMING AND OUTGOING DATA COM.
A0346/18	181010 DAR ES SALAAM FIR HTDC 1810101344/1811081530 EST NIL AIRAC PUBLICATION EFFECTIVE DATE 08 NOV 2018. (REF: AIP GEN 3.1 – 4).
A0341/18	181005 MWANZA HTMW 1810050430/1901051630 EST DLY 0430–1630 RWY 12/30 OPR BUT CTN ADVISED DUE CONST OF NEW CARGO APN TWY WIP WITHIN THE STRIP AT THE THR OF RWY 12 (NORTH/WEST SIDE). PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0339/18	181003 JULIUS NYERERE INTL AIRPORT HTDA 1810030756/1901031530 EST GP ILS RWY 05 FREQ 329.6 MHZ OPR ON SINGLE SYSTEM ONLY.
A0338/18	181002 DAR ES SALAAM FIR HTDC 1810021100/1901041530 EST AR 391 KHZ NDB TEMPO WITHDRAWN. (REF: AIP HTAR AD 2.19).
A0337/18	181001 MWANZA HTMW 1810011300/1901011530 EST FIRE FIGHTING AND RESCUE SER CHANGED TO CAT 8. (REF: AIP HTMW AD 2.6)

A0335/18	180929 JULIUS NYERERE INTL AIRPORT HTDA 1809290719/1812281530 EST AWOS (AUTOMATIC WEATHER OBSERVING SYSTEM) U/S.
A0334/18	180928 MWANZA HTMW 1809290300/1812311530 EST DLY 0300-1530 TURNING AREA HAS BEEN ESTABLISHED AT THE END OF RWY 12 WITH A LEN OF 500M.
A0333/18	180928 DAR ES SALAAM FIR HTDC 1809281432/1812281530 EST ZZ 385 KHZ NDB U/S.
A0318/18	180922 DAR ES SALAAM FIR HTDC 1809221130/1812211530 EST FLY540 TANZANIA HAS CHANGED NAME TO FASTJET AIRLINE LTD: THREE LETTER DESIGNATOR IS FTZ AND TELEPHONE DESIGNATOR GREY BIRD.
A0306/18	180911 MWANZA HTMW 1809111510/1812111530 EST THR RWY 12 DISPLACED BY 300M DUE WIP. DECLARED DIST TO READ AS FLWS.: RWY TORA TODA ASDA LDA 12 2900M 2900M 2900M 2700M 30 2900M 2900M 2900M 2700M (REF: AIP HTMW AD 2.13).
A0303/18	180905 DAR ES SALAAM FIR HTDC 1809050500/1812051300 EST MON – FRI 0500 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM HTDA COORD 065241S 0391209E TO HTNG COORD 0643S 03808E AND BACK TO HTDA, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. FM 1500FT TO 7000FT
A0302/18	180905 DAR ES SALAAM FIR HTDC 1809050500/1812051300 EST DLY 0500-1300 DANGER AREA HTD9, HTD10 AND HTD11 ACTIVATED (REF AIP ENR 5.1-3) FM GND TO 20000FT.
A0301/18	180905 DAR ES SALAAM FIR HTDC 1809050500/1812051300 EST DLY 0500-1300 MIL TRAINING FLT WILL TAKE PLACE FM HTMW COORD 022638S 0325554E TO THE AREA HTD9, HTD10, HTD11 AND BACK TO HTMW, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. FM GND TO 10000FT.
A0300/18	180905 DAR ES SALAAM FIR HTDC 1809050400/1812051300 EST DLY 0400 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM TANGA WI AN AREA ENCLOSED WITH THE FOLLOWING COORD:- 05 02 24.705S 038 59 05.881E 04 56 35.986S 038 48 33.782E 05 22 27.105S 038 58 33.955E 05 11 02.295S 039 02 26.620E, PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. CIVILIAN OPS AT

	HTTG COMMENCE AT NML TIME 0430 UTC, FM GND TO 6000FT.
A00295/18	180831 KILIMANJARO INTL AIRPORT HTKJ 1808311030/1811301530 EST ATIS U/S.
A0280/18	180816 KILIMANJARO INTL AIRPORT HTKJ 1808160900/1811161530 EST THR LGT RWY 27 U/S.
A0279/18	180816 KILIMANJARO INTL AIRPORT HTKJ 1808160900/1811161530 EST APPROACH LGT RWY 27 U/S.
A0275/18	180814 MWANZA HTMW 1808141242/1811121530 EST APCH LGT RWY 30 REMOVED DUE EXCAVATION AND BACKFILLING WIP ON THE EXTENDED PART OF THE END OF RWY 12.
SERIES:B	2018: 0060, 0059, 0053, 0051 AND 0050 2017: 0057 2016: 0097 AND 0095
B0060/18	181105 DODOMA AIRPORT HTDO 1811050930/ PERM FREQ 119.2MHZ (DODOMA TWR) CHANGED TO 133.0MHZ. (REF AIP HTDO AD 2.18)
B0059/18	181101 DAR ES SALAAM FIR HTDC 1811010000/1811302359 EST CHECKLIST OF NOTAM SERIES B IN FORCE ON NOVEMBER 01 2018 YEAR=16 0095 0097 YEAR=17 0057 YEAR=18 0050 0051 0053 LATEST PUBLICATIONS: AIP AMENDMENT NR 0065/18 AIP SUPPLEMENT NR 0021/18 AIC NR 0008/18 CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11

	<p>2013: 3 7 AND 9 2014: 3 4 AND 10 2015: 5 2017: 4 6 8 9 10 11 AND 12 2018: 1 2 3 4 5 7 AND 8</p> <p>CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 7 8 9 12 16 17 AND 18 2016: 4 9 15 AND 16 2017: 3 AND 17 2018: 9 11 16 17 19 AND 21</p>
B0053/18	<p>180905 SONGWE HTGW 1809050815/1812051530 EST PAPI RWY 09 U/S.</p>
B0051/18	<p>180831 MTWARA HTMT 1808310925/1811301530 EST AD LICENCE HAVE BEEN EXTENDED UP TO 30 NOVEMBER 2018.</p>
B0050/18	<p>180828 MTWARA HTMT 1808290300/1811211530 EST CONST OF SITE CAMP FOR AD UPGRADE AND REHABILITATION WIP. FM GND TO 33FT AT THE AREA BOUNDED BY THE FLW COORD:- 10 20 30.02S 040 10 35.57E 10 20 40.37S 040 10 34.94E 10 20 40.00S 040 10 26.64E 10 20 29.38S 040 10 27.33E.</p>
B0057/17	<p>170307 DODOMA HTDO 1706060937/PERM DUE TO THE EXTENSION OF RWY BY 500M DECLARED DIST NOW HAVE CHANGED TO: RWY TODA TORA ASDA LDA 09 2250M 2250M 2250M 2250M 27 2450M 2450M 2450M 2250M (REF: AIP HTDO AD 2.13).</p>
B0097/16	<p>160909 DODOMA HTDO 1609091042/PERM THR COORD AND MAG BRG HAS NOW CHANGED AS FLWS:- RWY THR COORD MAG BRG 09 061012.7860S 0354437.1160E 091 DEG 27 061014.7900S 0354556.4960E 272 DEG (REF: AIP HTDO AD 2.12 AND 2-6).</p>
B0095/16	<p>160909 DODOMA HTDO 1609090857/PERM RWY 10/28 HAVE NOW REALIGNED TO 09/27. (REF: AIP HTDO AD 2.10, 2.12, 2.14 AND 2-6).</p>

<p>SERIES: C</p>	<p>2018: 0071, 0070 AND 0066</p>
<p>C0071/18</p>	<p>181101 DAR ES SALAAM FIR HTDC 1811010000/1811302359 EST CHECKLIST OF NOTAM SERIES C IN FORCE ON NOVEMBER 01 2018 YEAR=18 0066 0070</p> <p>LATEST PUBLICATIONS: AIP AMENDMENT NR 0065/18 AIP SUPPLEMENT NR 0021/18 AIC NR 0008/18</p> <p>CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 AND 10 2015: 5 2017: 4 6 8 9 10 11 AND 12 2018: 1 2 3 4 5 7 AND 8</p> <p>CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 7 8 9 12 16 17 AND 18 2016: 4 9 15 AND 16 2017: 3 AND 17 2018: 9 11 16 17 19 AND 21</p>
<p>C0070/18</p>	<p>181010 BUTURI HTXX 1810101337/1812311530 EST BUTURI AIRSTRIP LICENCE HAVE BEEN EXTENDED UP TO 31 DEC 2018.</p>
<p>C0066/18</p>	<p>180930 KIPILI (GEORGE VINEYARD) HTXX 1809300944/1812311530 EST KIPILI (GEORGE VINEYARD) AIRSTRIP LICENCE HAS BEEN EXTENDED UP TO 31 DEC 2018.</p>
<p>LATEST PUBLICATIONS: AIP AMENDMENT NR 0065/18 AIP SUPPLEMENT NR 0021/18</p>	

AIC NR 0008/18

CHECKLIST OF VALID AICS:

YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43
46 47 51 53 55 AND 56
2001: 3
2002: 2 AND 4
2003: 3 7 8 13 AND 14
2004: 5 AND 8
2005: 4 AND 12
2006: 8 9 AND 10
2007: 8
2008: 3 6 8 AND 10
2009: 4 7 8 10 12 13 AND 14
2010: 3 AND 4
2011: 3 4 AND 5
2012: 10 AND 11
2013: 3 7 AND 9
2014: 3 4 AND 10
2015: 5
2017: 4 6 8 9 10 11 AND 12
2018: 1 2 3 4 5 7 AND 8

CHECKLIST OF VALID AIP SUPPLEMENTS:

YEAR 2006: 5 AND 15
2007: 13
2009: 10
2010: 20
2013: 11 AND 13
2014: 2 AND 4
2015: 7 8 9 12 16 17 AND 18
2016: 4 9 15 AND 16
2017: 3 AND 17
2018: 9 11 16 17 19 AND 21

***** END *****