



TEL: 255 22 2110223/224  
FAX: 255 22 2110264  
AFTN: HTDAYNYX  
E-mail: [tcaa.dia@tcaa.go.tz](mailto:tcaa.dia@tcaa.go.tz)  
[nofdia@tcaa.go.tz](mailto:nofdia@tcaa.go.tz)  
Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA**  
**TANZANIA CIVIL AVIATION AUTHORITY**  
Aeronautical Information Management  
International NOTAM Office  
P. O. Box 18001,  
DAR ES SALAAM  
TANZANIA

**DAILY NOTAM**

**UPDATE**

**14 MARCH 2018**

**Document No:**  
**TCAA/FRM/ANS/AIM-33**

**Title: Daily List of Valid NOTAM**

**Page 1 of 8**

THE FOLLOWING NOTAM SERIES (A, B & C) WERE STILL VALID AT 0001 UTC.

SERIES: A	2018: 0090, 0089, 0088, 0087, 0086, 0080, 0079, 0078, 0077, 0076, 0075, 0074, 0072, 0071, 0070, 0059, 0054, 0053, 0052, 0051, 0043, 0039, 0025, 0024, 0023 AND 0007. 2017: 0375, 0360 AND 0060
A0090/18	180313 MWANZA HTMW 1803140500/1805221500 DLY 0500-1500 DRONE FLT WILL TAKE PLACE FM MWANZA 2 30 56.4S 32 54 01.5E TO NANSIO 2 05 30.2S 33 05 42.1E WI AREA ENCLOSED IN THE FOLLOWIN COORDINATES 2 05 01.3S 33 04 56.2E 2 05 18.6S 33 06 16.3E 2 25 08.3S 32 53 14.5E 2 31 59.0S 32 54 58.8E 2 32 14.9S 32 52 39.6E 2 24 20.2S 32 51 49.7E PILOTS TO EXER CTN AND ADHERE TO ATC INSTRUCTIONS. FM GND TO 500FT
A0089/18	180309 KILIMANJARO INTL AIRPORT HTKJ 1804300400/1805141500 DLY 30 APR-14 MAY 2018 0400-1500 LOC (ILS) RWY 09 OPR BUT GND CHECKED ONLY, AWAITING FLTCK. PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0088/18	180309 KILIMANJARO AIRPORT HTKJ 1804300400/1805141500 DLY 30 APR-14 MAY 2018 0400-1500 GP (ILS) RWY 09 OPR BUT GND CHECKED ONLY, AWAITING FLTCK. PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0087/18	180309 DAR ES SALAAM INTL AIRPORT HTDA 1804300400/1805141500 DLY 30 APR-14 MAY 2018 0400-1500 LOC (ILS) RWY 05 OPR BUT GND CHECKED ONLY, AWAITING FLTCK. PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0086/18	180309 DAR ES SALAAM INTL AIRPORT HTDA 1804300400/1805141500 DLY 30 APR-14 MAY 2018 0400-1500 GP (ILS) RWY 05 OPR BUT GND CHECKED ONLY, AWAITING FLTCK. PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.

This is a controlled Document

A0080/18	180307 MWANZA HTMW 1803070730/1806071530 EST RWY END LGT RWY 12 TEMPO SHIFTED BY 30M INWARD FM THE BEGINNING OF RWY 30 DUE WIP. (REF: AIP HTMW AD 2.14).
A0079/18	180307 MWANZA HTMW 1803070735/1806071530 EST THR RWY 30 DISPLACED BY 300M DUE WIP. DECLARED DIST TO READ AS FLWS.: RWY TORA TODA ASDA LDA 12 3270M 3270M 3270M 3108M 30 3270M 3270M 3270M 3000M (REF: AIP HTMW AD 2.13).
A0078/18	170305 DAR ES SALAAM FIR HTDC 1703050500/1806051300 EST MON – FRI 0500 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM HTDA COORD 065241S 0391209E TO HTNG COORD 0643S 03808E AND BACK TO HTDA, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS, FM 1500FT TO 7000FT.
A0077/18	180305 DODOMA HTDO 1803050836/1804041530 EST DO 373 KHZ NDB U/S.
A0076/18	170305 DAR ES SALAAM FIR HTDC 1703050500/1806051300 EST DLY 0500-1300 DANGER AREA HTD9, HTD10 AND HTD11 ACTIVATED (REF AIP ENR 5.1-3) FM GND TO 20000FT.
A0075/18	170305 DAR ES SALAAM FIR HTDC 1703050500/1806051300 EST DLY 0500-1300 MIL TRAINING FLT WILL TAKE PLACE FM HTMW COORD 022638S 0325554E TO THE AREA HTD9, HTD10, HTD11 AND BACK TO HTMW, PILOTS TO EXP DLA AND STRICTLY ADHERE TO ATC INSTRUCTIONS, FM GND TO 10000FT.
A0074/18	170305 DAR ES SALAAM FIR HTDC 1703050400/1806051300 EST DLY 0400 – 1300 MIL TRAINING FLT WILL TAKE PLACE FM TANGA WI AN AREA ENCLOSED WITH THE FOLLOWING COORD:- 05 02 24.705S 038 59 05.881E 04 56 35.986S 038 48 33.782E 05 22 27.105S 038 58 33.955E 05 11 02.295S 039 02 26.620E, PILOTS TO AVOID THE AREA AND STRICTLY ADHERE TO ATC INSTRUCTIONS. CIVILIAN OPS AT HTTG COMMENCE AT NML TIME 0430 UTC, FM GND TO 6000FT.

A0072/18	<p>180302 DAR ES SALAAM FIR HTDC 1803020540/1803291530 EST NIL AIRAC PUBLICATION EFFECTIVE DATE 29 MAR 2018. (REF: AIP GEN 3.1-4).</p>
A0071/18	<p>180301 DAR ES SALAAM FIR HTDC 1803010000/1803312359 EST CHECKLIST OF NOTAM SERIES A IN FORCE ON MARCH.1 2018 YEAR=17 0060 0339 0340 0341 0342 0346 0347 0360 0375 YEAR=18 0006 0007 0023 0024 0025 0028 0029 0039 0043 0051 0052 0053 0054 0059 0060 0062 0065 0070 AND 0071</p> <p>LATEST PUBLICATIONS: AIP AMENDMENT NR 0063/18 AIP SUPPLEMENT NR 0003/18 AIC NR 0005/18</p> <p>CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 5 AND 10 2015: 3 AND 5 2017: 4 6 8 9 10 11 AND 12 2018: 1 2 3 4 AND 5</p> <p>CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 6 7 8 9 12 16 17 AND 18 2016: 4 9 15 AND 16 2017: 2 3 14 AND 17 2018: 2 AND 3</p>
A0070/18	<p>180228 KILIMANJARO INTL AIRPORT HTKJ 1802281423/1805311530 EST ATIS U/S.</p>
A0059/18	<p>180219 KILIMANJARO INTL AIRPORT HTKJ 1802190500/1805101600 EST DLY 0500-1600 ATC TRAINING WILL TAKE PLACE AT HTKJ TWR 119.9 MHZ. PILOTS ADVISED TO COOPERATE.</p>

A0054/18	170214 ARUSHA HTAR 1702140746/1805161530 EST AR 391 KHZ NDB TEMPO WITHDRAWN. (REF: AIP HTAR AD 2.19).
A0053/18	180213 KILIMANJARO INTL AIRPORT HTKJ 1802131414/1805130500 EST THR LGT RWY 27 U/S.
A0052/18	180213 KILIMANJARO INTL AIRPORT HTKJ 1802131411/1805130500 EST APPROACH LGT RWY 27 U/S.
A0051/18	180213 KILIMANJARO INTL AIRPORT HTKJ 1802130923/1805101600 EST DLY 0500-1600 ATC TRAINING WILL TAKE PLACE AT HTKJ APP 120.1 MHZ. PILOTS ADVISED TO COOPERATE.
A0043/18	180209 MWANZA HTMW 1802091800/1805111530 EST APCH LGT RWY 30 REMOVED DUE EXCAVATION AND BACKFILLING WIP ON THE EXTENDED PART OF RWY 30.
A0039/18	180209 JULIUS NYERERE INTL AIRPORT HTDA 1802090706/1803281530 EST AD OPR BUT CTN ADVISED DUE CONST WIP FM GATE NR. 18 ADJ THE ROAD WAY ON THE GRASS TERRAIN ABT 600M ALONG THE ROAD TO RADAR/ACC BLDG.
A0025/18	180131 DAR ES SALAAM FIR HTDC 1801310844/1804201530 EST PSR U/S.
A0024/18	180130 JULIUS NYERERE INTL AIRPORT HTDA 1801301230/1803301530 EST PORTION OF TWY 'P' FM GATE 'E' TO INT OF RWY 23 CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0023/18	180130 JULIUS NYERERE INTL AIRPORT HTDA 1801301230/1803301530 EST GATE 'E' CLSD DUE WIP, PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0007/18	180105 MWANZA HTMW 1801070430/1804051630 EST DLY 0430-1630 RWY 12/30 OPR BUT CTN ADVISED DUE CONST OF NEW CARGO APN TWY WIP WITHIN THE STRIP AT THE THR OF RWY 12 (NORTH/WEST SIDE). PILOTS STRICTLY ADHERE TO ATC INSTRUCTIONS.
A0375/17	171229 ZANZIBAR INTL AIRPORT HTZA 1712290617/1803291530 EST ZZ 385 KHZ NDB U/S.
A0360/17	171214 JULIUS NYERERE INTL AIRPORT HTDA 1712141015/1803301530 EST AWOS (AUTOMATIC WEATHER OBSERVING SYSTEM) U/S.

A0060/17	170321 JULIUS NYERERE INTL AIRPORT HTDA 1703210712/ <b>PERM</b> DUE TO APN LAYOUT CHANGES FM ORIGINAL APN LAYOUT ON AEROBRIDGES D1, D2, E1, E2 AND E3, PILOTS ADVISED TO FLW MARSHALLER'S INSTRUCTIONS.
<b>SERIES:B</b>	<b>2018: 0013, 0012 AND 0011</b> <b>2017: 0057</b> <b>2016: 0097 AND 0095</b>
B0013/18	180305 SONGWE HTGW 1803050917/1806051530 EST PAPI RWY 09 U/S.
B0012/18	180201 DAR ES SALAAM FIR HTDC 1803010000/1803312359 EST CHECKLIST OF NOTAM SERIES B IN FORCE ON MARCH.1 2018 YEAR=16 0095 0097 YEAR=17 0057 YEAR=18 0010 0011 0012  LATEST PUBLICATIONS: AIP AMENDMENT NR 0063/18 AIP SUPPLEMENT NR 0003/18 AIC NR 0005/18  CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14 2010: 3 AND 4 2011: 3 4 AND 5 2012: 10 AND 11 2013: 3 7 AND 9 2014: 3 4 5 AND 10 2015: 3 AND 5 2017: 4 6 8 9 10 11 AND 12 2018: 1 2 3 4 AND 5  CHECKLIST OF VALID AIP SUPPLEMENTS: YEAR 2006: 5 AND 15 2007: 13 2009: 10 2010: 20 2013: 11 AND 13 2014: 2 AND 4 2015: 6 7 8 9 12 16 17 AND 18 2016: 4 9 15 AND 16 2017: 2 3 14 AND 17

	2018: 2 AND 3
B0011/18	180226 TABORA HTTB 1802260740/1803261530 EST RWY 08/26 AVBL FOR TAX ONLY.
B0057/17	170307 DODOMA HTDO 1706060937/ <b>PERM</b> DUE TO THE EXTENSION OF RWY BY 500M DECLARED DIST NOW HAVE CHANGED TO: RWY TODA TORA ASDA LDA 09 2250M 2250M 2250M 2250M 27 2450M 2450M 2450M 2250M (REF: AIP HTDO AD 2.13).
B0097/16	160909 DODOMA HTDO 1609091042/ <b>PERM</b> THR COORD AND MAG BRG HAS NOW CHANGED AS FLWS:- RWY THR COORD MAG BRG 09 061012.7860S 0354437.1160E 091 DEG 27 061014.7900S 0354556.4960E 272 DEG (REF: AIP HTDO AD 2.12 AND 2-6).
B0095/16	160909 DODOMA HTDO 1609090857/ <b>PERM</b> RWY 10/28 HAVE NOW REALIGNED TO 09/27. (REF AIP HTDO AD 2.10, 2.12, 2.14 AND 2-6).
<b>SERIES: C</b>	<b>2018: 0017, 0016 AND 0015</b>
C0017/18	180201 DAR ES SALAAM FIR HTDC 1803010000/1803312359 EST CHECKLIST OF NOTAM SERIES C IN FORCE ON MARCH.1 2018 YEAR=18 0015 0016 0017  LATEST PUBLICATIONS: AIP AMENDMENT NR 0063/18 AIP SUPPLEMENT NR 0003/18 AIC NR 0005/18  CHECKLIST OF VALID AICS: YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43 46 47 51 53 55 AND 56 2001: 3 2002: 2 AND 4 2003: 3 7 8 13 AND 14 2004: 5 AND 8 2005: 4 AND 12 2006: 8 9 AND 10 2007: 8 2008: 3 6 8 AND 10 2009: 4 7 8 10 12 13 AND 14

	<p>2010: 3 AND 4                  2011: 3 4 AND 5                  2012: 10 AND 11                  2013: 3 7 AND 9                  2014: 3 4 5 AND 10                  2015: 3 AND 5                  2017: 4 6 8 9 10 11 AND 12                  2018: 1 2 3 4 AND 5</p> <p><b>CHECKLIST OF VALID AIP SUPPLEMENTS:</b>                  YEAR 2006: 5 AND 15                  2007: 13                  2009: 10                  2010: 20                  2013: 11 AND 13                  2014: 2 AND 4                  2015: 6 7 8 9 12 16 17 AND 18                  2016: 4 9 15 AND 16                  2017: 2 3 14 AND 17                  2018: 2 AND 3</p>
--	--

C0016/18	<p>180222LAKE MANYARA HTLM                  1802220331/1803221530 EST                  THR RWY 12 DISPLACED BY 300M DUE POT HOLES AND STREAMS. DECLARED DIST TO READ AS FLW.:</p> <table border="0"> <tr> <td>RWY</td> <td>TORA</td> <td>TODA</td> <td>ASDA</td> <td>LDA</td> </tr> <tr> <td>12</td> <td>920M</td> <td>920M</td> <td>920M</td> <td>920M</td> </tr> <tr> <td>30</td> <td>920M</td> <td>920M</td> <td>920M</td> <td>920M</td> </tr> </table> <p>(REF: AIP HTLM AD 2.13).</p>	RWY	TORA	TODA	ASDA	LDA	12	920M	920M	920M	920M	30	920M	920M	920M	920M
RWY	TORA	TODA	ASDA	LDA												
12	920M	920M	920M	920M												
30	920M	920M	920M	920M												

C0015/18	<p>180215 ARUSHA HTAR                  1802150900/<b>PERM</b>                  THE TEL AND FAX NR FOR AIS OFFICE IS NOW +255 27 2970106                  (REF: AIP GEN 3.1-6).</p>
----------	--

<p><b>LATEST PUBLICATIONS:</b>                  AIP AMENDMENT NR 0063/18                  AIP SUPPLEMENT NR 0003/18                  AIC NR 0005/18</p> <p><b>CHECKLIST OF VALID AICS:</b>                  YEAR 2000: 3 6 7 8 9 10 11 12 13 14 15 16 17 18 20 21 28 29 30 31 33 35 36 37 40 41 43                  46 47 51 53 55 AND 56                  2001: 3                  2002: 2 AND 4                  2003: 3 7 8 13 AND 14                  2004: 5 AND 8                  2005: 4 AND 12                  2006: 8 9 AND 10                  2007: 8</p>	
--	--

2008: 3 6 8 AND 10  
2009: 4 7 8 10 12 13 AND 14  
2010: 3 AND 4  
2011: 3 4 AND 5  
2012: 10 AND 11  
2013: 3 7 AND 9  
2014: 3 4 5 AND 10  
2015: 3 AND 5  
2017: 4 6 8 9 10 11 AND 12  
2018: 1 2 3 4 AND 5

CHECKLIST OF VALID AIP SUPPLEMENTS:

YEAR 2006: 5 AND 15  
2007: 13  
2009: 10  
2010: 20  
2013: 11 AND 13  
2014: 2 AND 4  
2015: 6 7 8 9 12 16 17 AND 18  
2016: 4 9 15 AND 16  
2017: 2 3 14 AND 17  
2018: 2 AND 3

\*\*\*\*\* END \*\*\*\*\*