

 FAX: (255 22) 2844300, 2844302 PHONE: (255 22) 2198100 AFS: HTDQYOYO Email: tcaa@tcaa.go.tz , ais@tcaa.go.tz Website: www.tcaa.go.tz	UNITED REPUBLIC OF TANZANIA TANZANIA CIVIL AVIATION AUTHORITY Aeronautical Information Management Nyerere/ Kitunda Road Junction Aviation House, 1st Floor, P.O. Box 2819, DAR ES SALAAM	AIP Supplement 07/25 Published on 24 January 2025
Document No: TCAA/FRM/ANS/AIM - 56	Title: AIP Supplement	Page 1 of 1

AERODROMES (AD)

S07 Shinyanga Airport – HTSY

Effective 24th January 2025 to 31st March 2025, Shinyanga Airport closed for major rehabilitation and upgrading.

The rehabilitation and upgrading will involves

- i. Reconstruction of the existing RWY 11/29, 2000M length and 30M wide including associated Taxiways and Apron areas;
- ii. Earthworks for Runway Shoulders, Strip and RESA;
- iii. Installation of Signages and Aerodrome Ground Lights for Runway, Apron, Taxiways, PAPI, VOR/DME;
- iv. Installation of Visual Aids;
- v. Construction of Terminal Building and Control Tower.

(Cancel AIP SUP 05/25)

(