



Fax: (255) 22 2844300, 2844302  
PHONE: (255) 22 2198100, 2844291  
AFS: HTDQYOYO  
E-MAIL: [tcaa@tcaa.go.tz](mailto:tcaa@tcaa.go.tz), [ais@tcaa.go.tz](mailto:ais@tcaa.go.tz)  
Website: [www.tcaa.go.tz](http://www.tcaa.go.tz)

**UNITED REPUBLIC OF TANZANIA**  
TANZANIA CIVIL AVIATION AUTHORITY  
Aeronautical Information Management  
Nyerere/ Kitunda Road Junction  
Aviation House, 1st Floor,  
P.O. Box 2819, DAR ES SALAAM

**AIP  
Supplement**  
**20 – 22/23**  
**14 December 2023**

Document No:  
TCAA/FRM/ANS/AIM-56

Title: **AIP Supplement**

Page 1 of 1

## AERODROMES (AD)

### **S20 Morogoro Airport – HTMG**

AN ELECTRIC PWR TRANSMISSION LINE WITH A SERIES OF AERIAL MASTS  
ERECTED AT RIGHT SIDE RWY 03 AT A DIST OF 700M FM RWY CL AND APCH  
SIDE RWY 03 WITH HGT OF 200FT AGL AND DIST OF 900M FM THR RWY 03.  
PILOTS ADVISED TO TAKE CTN DRG LDG/TKOF.  
FM GND TO 200FT AGL. **(REF: AIP HTMG AD 2.10)**  
**(Cancel NOTAM C0016)**

### **S21 Julius Nyerere International Airport – HTDA**

TRANSITION LVL CHANGED FM FL030 TO FL040.  
**(Cancel NOTAM A0190)**

### **S22 Julius Nyerere International Airport – HTDA**

TRANSITION ALT CHANGED FM 2500FT TO 3500FT.  
**(Cancel NOTAM A0189)**